

Date : 22/09/2022

*Xiao Tony*

TO: **AIG Asia Pacific Insurance Pte Ltd**  
**AIG Building**  
**78 Shenton Way, #07-16**  
**Singapore 079120**

Our Customer : Secretary of The Synod Diocese of Singapore

Vehicle No : S16E

Model : Toyota Camry Hybrid 2.5 Ascent

Manufacture Year : 2020

Date of Accident : 15/09/2022

Total Estimate Repair Days : 5

Total Pages : 1

Attn : Motor Claim Department  
 Fax : 6415 3727

Re: Repair Estimate For Third Party Claim against S1915CD

No.	Item Descriptions	Qty	Unit Price	Amount	Remarks From Surveyor
<b>A. Spare Parts</b>					
1	Rear bumper <i>Del</i>	1	\$527.00	\$527.00	✓
2	Rear bumper side retainer RH <i>Free 45</i>	1	45	45 <del>\$0.00</del>	+
3	Rear bumper side retainer LH <i>Free 45</i>	1	45	45 <del>\$0.00</del>	+
4	Rear bumper spoiler <i>Del</i>	1	\$393.00	\$393.00	✓
5	Rear bumper inner cover <i>new</i>	1	303	303	+
6	Rear bumper reflector RH <i>new</i>	1	\$65.00	\$65.00	+
7	Rear bumper reinforcement <i>Del</i>	1	\$277.00	\$277.00	✓
8	Rear end panel <i>new</i>	1	\$651.00	\$651.00	+
9	Rear "Toyota" logo <i>Free</i>	1	\$60.00	\$60.00	✓
10	Rear "Hybrid" emblem <i>Free</i>	1	\$60.00	\$60.00	✓
11	Rear "Camry" emblem <i>Free</i>	1	\$72.00	\$72.00	✓
12	Boot lid <i>Free</i>	1	\$1,143.00	\$1,143.00	+
13	Boot lid reflector RH <i>Free</i>	1	\$315.00	\$315.00	+
14	Tail lamp RH <i>Free</i>	1	\$483.00	\$483.00	+
			<b>Sub Total</b>	<b>\$4,046.00</b>	
			Less 25%	\$1,011.50	
			<b>Sub Total 1</b>	<b>\$3,034.50</b>	
<b>B. Spare Parts (S/Nett)</b>					
1	Reverse sensor (set) <i>new</i>	1	\$250.00	\$250.00	200
2	Rear bumper clip <i>new</i>	10	\$5.00	\$50.00	30
3	Rear end panel garnish clip <i>new</i>	8	\$5.00	\$40.00	+
			<b>Sub-Total 2</b>	<b>\$340.00</b>	
			<b>Total for Parts</b>	<b>\$3,374.50</b>	
<b>C. Labour</b>					
1	To check wiring.			\$60.00	30
2	Panel beating charges to remove and replace, to cut and weld, to knock and reshape damaged parts & areas.			\$400.00	200
3	Spray painting all affected parts & areas.			\$600.00	400
4	To spray anti-rust undercoat.			\$30.00	+
			<b>Total Labour</b>	<b>\$1,090.00</b>	630
			<b>Total Repair Cost</b>	<b>\$4,464.50</b>	

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

*total: 1901.75 Admin by  
 4/5 / 1.51C. 4/5 27/09/22.  
 03 Days.*