

LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 1

PRE-REPAIR INSPECTION REPORT					
	AXA INSURANCE		Ref:	CS3/ASM22009424/Gvy3m4	
	8 SHENTON WAY SINGAPORE 0688		Date:	28/09/2022	
	ATTN: LOW GARN		Code:	ASM	
1.	Policy Particulars :- (THIRD PARTY CLAIM)				
	Insured Veh.	SHA 3079D	Veh. Inspected		SMS 5708E
	Policy No.	VFX/P2419138	Coverage (\$)		0.00
	Claim No.	S2M04BKG	Excess (\$)		0.00
	Assign From	LOW GARNET	Assign Date		26/09/2022
2. Vehicle Particulars & Condition					
	Make & Model	HONDA SHUTTLE HYBRID 1.5	c.c		1496
	Engine No.	HIDDEN	Year of Reg.		2020
	Chassis No.	GP72002112	Colour		WHITE
	Odometer	-	Steering		IN ORDER
	Brakes	IN ORDER	Modification		NIL
	General	GOOD			
3.	Conditions of Tyres				
		Size	Make		Balance
	R/H Front Tyre	185/60 R15	GITI		6 mm
	L/H Front Tyre	185/60 R15	GITI		6 mm
	R/H Rear Tyre	185/60 R15	DAVANTI		6 mm
	L/H Rear Tyre	185/60 R15	DAVANTI		6 mm
4.	Description of Damages				
	THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION.				
5. General Information					
	Accident Date	22/09/2022	Inspect Date / 1	Time	26/09/2022 (04:30 PM)
	Survey held at	365 AUTOMOTIVE PTE LTD			
		25 KAKI BUKIT ROAD 4 #01-55 SYNERGY @KB SINGAPORE 417800			
5a.	Remarks				
	A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. B) THE REPAIR ESTIMATE WAS NOT PRESENTED AT THE TIME OF INSPECTION. THE REPAIRER WAS TOLD TO PREPARE THE ESTIMATE. C) ENCLOSED PLEASE FIND DAMAGED VEHICLE PHOTOGRAPHS. D) THE ESTIMATED REPAIR COST OF THE DAMAGED VEHICLE IS IN THE REGION OF \$3,000-\$4,000				
5b.	. Estimate Days of Repair				
	ESTIMATED NORMAL PERIOD FOR REPAIR: 5 Working Days				
				_	

Report Ref No. CS3/ASM22009424/Gvy3m4

Inspected By

XING GUO QIANG

K.K.LAU CPT(RET)

M.MATAI, AMSAE-A
Automotive Assessor

 $BEng(Hons), B. Bus, MBA, PEng, PE, \, MInstAEA, MASME, MIRTE$

REGD Auto Consultant-SAE, Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contact or tort, is accepted to any third party who may reply on the Report wholly or in part. Any third party acting or replying on this Report, in whole or in part, does so at his or her own risk.