

TO : ALLIANZ GLOBAL CORPORATE & SPECIALTY AG

FAX NO:

ESTIMATE REPORT 1ST Quotation

28/09/2022 18:31

OWNER'S PARTICULARS

JOB-NO: 85008943

NAME: SINGAPORE ELECTRIC VEHIC CONTACT:

Page 1 of 3

ADDRESS: 152 UBI AVENUE 4
SINGAPORE (408826)

NOEMAIL@NOEMAIL.CO

VEHICLE DETAILS

LICENSE NO: SLV1072C

TRANS: AUTO

CHASSIS: LC0CE4DB2H1026306

MAKE / MODEL: BYD / e6

ENGINE: BYDTC90B117000298

OWNER'S INSURER: ALLIANZ GLOBAL CORPORATE & SPECIALT

JOB-CODE: OD

SA: Ding Auto User 2

CLAIM DETAILS

DESCRIPTION	QTY	QUOTED COSTS	MARK UP	MARKUP PRICE	IND	SUR.DISP	REV PRICE
LABOUR							
1 TO STRAIGHTEN AND PANEL BEAT OF ACCIDENT AFFECTED AREA	1.00	3,000.00	0.00	3,000.00	1400	Y	_____
2 TO RUST PROOFING OF THE AFFECTED AREA	1.00	200.00	0.00	200.00	30	Y	_____
3 TO REMOVE AND REFIT OF NECESSARY ITEMS TO FACILITATE BODYWORK REPAIR	1.00	210.00	0.00	210.00	100	Y	_____
4 TO DIAGNOSTIC, CHECK WIRING AND LIGHTING SYSTEM AND CLEAR FAULT CODE	1.00	240.00	0.00	240.00	30	Y	_____
5 TO REFIT REAR REVERSE SENSOR	1.00	100.00	0.00	100.00	30	Y	_____
6 TO CONDUCT TYRE BALANCING AND WHEEL ALIGNMENT	1.00	120.00	0.00	120.00	80	Y	_____
7 TO REMOVE AND REFIT FRONT AND REAR QUARTER GLASS TO ENABLE BODYWORK REPAIR	1.00	180.00	0.00	180.00	100	Y	_____
8 TO REMOVE AND REFIT REAR WINDSCREEN GLASS TO ENABLE BODYWORK REPAIR	1.00	180.00	0.00	180.00	X	Y	_____
9 TO TRANSFER OF BOTH FRONT AND REAR DOOR MECHANISM TO NEW DOOR AND PERFORM WATER SEEPAGE TEST	1.00	220.00	0.00	220.00	100	Y	_____
10 TO VACUUM REAR DOOR GLASS SHARD AND WASH REAR SEAT	1.00	100.00	0.00	100.00	30	Y	_____
11 TO CHECK AND REPAIR WIRE HARNESS	1.00	150.00	0.00	150.00	X	Y	_____
12 TO RESPRAY REAR OUTER QUARTER PANEL	1.00	250.00	0.00	250.00	200	Y	_____
13 TO RESPRAY REAR INNER QUARTER PANEL	1.00	250.00	0.00	250.00	X	Y	_____
14 TO RESPRAY REAR DOOR PANEL	1.00	250.00	0.00	250.00	200	Y	_____
15 TO RESPRAY SIDE SKIRT RH	1.00	250.00	0.00	250.00	200	Y	_____
16 TO RESPRAY ROCKER PANEL OUTER RH	1.00	250.00	0.00	250.00	X	Y	_____
17 TO RESPRAY CENTER PILLAR OUTER RH	1.00	250.00	0.00	250.00	X	Y	_____
18 TO RESPRAY FRONT RH DOOR PANEL	1.00	250.00	0.00	250.00	200	Y	_____
19 TO RESPRAY REAR BUMPER	1.00	250.00	0.00	250.00	X	Y	_____
20 TO RESPRAY REAR BUMPER	1.00	250.00	0.00	250.00	X	Y	_____
21 TO RESPRAY FRONT AND REAR OUTER DOOR HANDLE AND COVER	1.00	250.00	0.00	250.00	60	Y	_____
22 TO RESPRAY REAR UPPER AND LOWER DOOR HINGE	1.00	250.00	0.00	250.00	X	Y	_____
23 TO RESPRAY FRONT BUMPER	1.00	250.00	0.00	250.00	X	Y	_____
24 TO RESPRAY FRONT LH FENDER PANEL	1.00	250.00	0.00	250.00	200	Y	_____

CLAIM DETAILS

DESCRIPTION	QTY	QUOTED COSTS	MARK UP	MARKUP PRICE	IND	SUR.DISP	REV PRICE
25 TO RESPRAY FRONT LH DOOR PANEL	1.00	250.00	0.00	250.00	200	Y	_____
26 TO RESPRAY SIDE SKIRT LH	1.00	250.00	0.00	250.00	200	Y	_____
27 TO RESPRAY FRONT WHEEL RIM	1.00	250.00	0.00	250.00	X	Y	_____
28 TO RESPRAY REAR WHEEL RIM	1.00	250.00	0.00	250.00	X	Y	_____
TOTAL:		8,950.00	0.00	8,950.00			_____

MATERIALS

1 REAR RH FENDER LINER	✓	CRU	1.00	92.40	9.24	101.64	Y	_____
2 REAR RH DOOR PANEL	✓	DD	1.00	1,372.00	137.20	1,509.20	Y	_____
3 REAR RH DOOR GLASS	✓	BR	1.00	154.00	15.40	169.40	Y	_____
4 REAR RH DOOR GLASS RUN	✓	CUT	1.00	58.04	5.80	63.84	Y	_____
5 REAR RH DOOR LOCK	?		1.00	102.68	10.27	112.95	Y	_____
6 REAR RH DOOR POWER WINDOW	?		1.00	196.00	19.60	215.60	Y	_____
REGULATOR MOTOR								
7 REAR RH DOOR INNER TRIM BOARD	✓	CRU	1.00	434.00	43.40	477.40	Y	_____
8 REAR RH OUTER DOOR GLASS MOULDING	✓	BT	1.00	107.96	10.80	118.76	Y	_____
9 REAR RH DOOR CHECK	X		1.00	37.34	3.73	41.07	Y	_____
10 REAR RH UPPER DOOR HINGE	?		1.00	11.68	1.17	12.85	Y	_____
11 REAR RH LOWER DOOR HINGE	?		1.00	11.68	1.17	12.85	Y	_____
12 REAR RH DOOR WIRE HARNESS	?		1.00	77.56	7.76	85.32	Y	_____
13 REAR RH DOOR REAR FRAME SECTION	✓	NEC	1.00	7.38	0.74	8.12	Y	_____
BLACK FILM								
14 REAR RH DOOR UPPER WINDOW FRAME	✓	NEC	1.00	7.48	0.75	8.23	Y	_____
BLACK FILM								
15 REAR RH DOOR FRAME WEATHERSTRIP	✓	CRU	1.00	249.80	24.98	274.78	Y	_____
16 REAR RH DOOR REAR GLASS GUIDE	✓	BT	1.00	25.64	2.56	28.20	Y	_____
CHANNEL								
17 REAR RH DOOR B PILLAR BLACK FILM	✓	NEC	1.00	7.38	0.74	8.12	Y	_____
18 REAR RH DOOR WINDOW LOWER FRONT	✓	NEC	1.00	16.88	1.69	18.57	Y	_____
GLASS CHANNEL GUIDE								
19 REAR RH DOOR INNER WEATHERSTRIP	✓	CUT	1.00	31.74	3.17	34.91	Y	_____
20 REAR RH OUTER DOOR HANDLE	?		1.00	62.54	6.25	68.79	Y	_____
21 FRONT RH DOOR PANEL	✓	DD	1.00	1,493.34	149.33	1,642.67	Y	_____
22 FRONT RH OUTER DOOR HANDLE	✓	CUT	1.00	188.94	18.89	207.83	Y	_____
23 FRONT RH OUTER DOOR GLASS MOULDING	✓	CUT	1.00	81.10	8.11	89.21	Y	_____
24 FRONT RH DOOR UPPER WINDOW FRAME	✓	NEC	1.00	8.96	0.90	9.86	Y	_____
BLACK FILM								
25 FRONT RH DOOR B-PILLAR BLACK FILM	✓	CUT	1.00	8.96	0.90	9.86	Y	_____
26 SIDE SKIRT RH	✓	BR	1.00	112.00	11.20	123.20	Y	_____
27 REAR RH WHEEL RIM	✓	CUT	1.00	373.34	37.33	410.67	Y	_____
28 FRONT LH FENDER PANEL	✓	BR	1.00	550.68	55.07	605.75	Y	_____
29 SIDE SKIRT LH	✓	BR	1.00	112.00	11.20	123.20	Y	_____
30 FRONT LH WHEEL RIM	✓	CUT	1.00	373.34	37.33	410.67	Y	_____
31 FRONT LH FENDER LINER	?		1.00	107.34	10.73	118.07	Y	_____
32 FRONT LH DOOR PANEL	X	repair	1.00	1,493.34	149.33	1,642.67	Y	_____
33 FRONT LH DOOR B PILLAR BLACK FILM	X		1.00	NN 8.96	0.90	9.86	Y	_____
34 FRONT LH DOOR UPPER WINDOW FRAME	X		1.00	NN 8.96	0.90	9.86	Y	_____
BLACK FILM								
35 SIDEWALL RH ASSY (rear fender)	✓	DD	1.00	4,927.12	492.71	5,419.83	Y	_____
36 REAR RH INNER DOOR GLASS MOULDING	✓	CUT	1.00	31.74	3.17	34.91	Y	_____
37 FRONT LH BUMPER RETAINER	X	NN	1.00	9.82	0.98	10.80	Y	_____
38 FRONT BUMPER COVER	X	NN	1.00	536.68	53.67	590.35	Y	_____
39 REAR QUARTER PANEL SEALANT	✓	NEC	2.00	120.00	0.00	40 120.00	S	Y
40 FRONT AND REAR QUARTER GLASS	✓	NEC	2.00	100.00	0.00	20 100.00	S	Y
PRIMER								
41 FRONT AND REAR QUARTER GLASS	X	NN	3.00	150.00	0.00	150.00	S	Y
SEALANT								
42 SIDE SKIRT CLIP SET	✓	NEC	1.00	50.00	0.00	20 50.00	S	Y
43 FRONT FENDER LINER CLIP SET	X	NN	1.00	55.00	0.00	55.00	S	Y
44 ROCKER PANEL SEALANT	X	NN	2.00	120.00	0.00	120.00	S	Y
45 SIDEWALL SEALANT	✓	NEC	4.00	200.00	0.00	30 200.00	S	Y

CLAIM DETAILS

DESCRIPTION	QTY	QUOTED COSTS	MARK UP	MARKUP PRICE	IND	SUR.DISP	REV PRICE
46 FRONT AND REAR DOOR MOULDING CLIP SET ✓	1.00	55.00	0.00	55.00	S	Y	
47 REAR DOOR INNER TRIM BOARD CLIP SET ✓	1.00	50.00	0.00	50.00	S	Y	
48 REAR FENDER LINER CLIP SET ✓	1.00	50.00	0.00	50.00	S	Y	
49 FRONT BUMPER CLIP SET X	1.00	55.00	0.00	55.00	S	Y	
TOTAL:		14,495.80	,349.07	15,844.87			
TOTAL PARTS & LABOUR :		23,445.80	1,349.07	24,794.87			

EXCESS/LOADING:S\$ 0.00

No. Of Day: _____

RE-SURVEY: BEFORE/AFTER PAINTING

PART-BY-PART OR LUMP SUM: S\$ _____

DATE OF SURVEY: ____ / ____ / ____

SURVEYED BY: _____

CONTACT NO: _____ FAX NO: _____

NOTE: LUMP SUM AMOUNT WOULD BE REVISED IF SUPPLEMENT REPAIR IS REQUIRED

DAuto002

Ding Auto User 2

ESTIMATOR

STA AUTOCENTRE

TEL:

FAX:

Steve (LKK)
26/09/22
OD - Not Authorise
Excess - ?
Part By Part
Resurvey Before Spray
12 days