

**Note: This document has not been finalised.****LKK Auto Consultants Pte Ltd** (Co.Reg.No:199607198R)51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park  
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

To: Allianz Insurance Singapore Pte. Ltd.  
79 Robinson Road #09-01  
Singapore 068897From: LKK Auto Consultants Pte Ltd  
51 Ubi Ave 1 #01-25  
Paya Ubi Industrial Park  
Singapore 408933

Attn: JANICE KOH

Date: 29 Sep 2022

**Preliminary Advice**

Vehicle No	: SLV1072C	Accident Date	: 24/09/2022
Make	: BYD E6H	Policy No.	: SPMF1000000503
Assignment Date	: 26/09/2022	Excess	: S\$2,000.00
Date of Inspection	: 26/09/2022	Est. Duration of Repair	: 12
Inspection At	: DING AUTOMOTIVE PTE LTD (HQ) 31 CORPORATION ROAD SINGAPORE 649825		

**Point of Impact / General Description of Damages**

Parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	24,794.87
Revised Amount	:S\$	14,418.22
Check Items (Estimated)	:S\$	626.43
Total	:S\$	15,044.65

Lump Sum Repair	:S\$	
-----------------	------	--

**Total Loss Consideration**

New for Old Value	:S\$	
Pre-Accident Value	:S\$	66,000.00
COE / PARF Rebate	:S\$	29,426.00
Salvage Value	:S\$	
Margin for Repair	:S\$	36,574.00

**Remarks**

- ( x ) The vehicle is repairable at our adjusted amount. We have also confirmed excess and policy coverage. Kindly let us have your authorisation.
- ( ) The vehicle is uneconomical to be repaired, you are advised to invite tender for the wreck.
- ( x ) Other comments :the vehicle repair on part by parts basis due to no second parts available. Please note that the preliminary advice amount (Revised & Check Items) stated are subject to part prices and labour cost check.