

**Note: This document has not been finalised.**

**LKK Auto Consultants Pte Ltd** (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

To: Allianz Insurance Singapore Pte.  
Ltd.  
79 Robinson Road #09-01  
Singapore 068897

From: LKK Auto Consultants Pte Ltd  
51 Ubi Ave 1 #01-25  
Paya Ubi Industrial Park  
Singapore 408933

Attn: Chan Kian Chuan

Date: 20 Oct 2022

**Preliminary Advice**

Insured : GBL1127A

Vehicle No

TP Vehicle : SBS3816U  
No

Accident Date : 16/09/2022

Make : VOLVO B9TL

Assignment Date : 26/09/2022

Date of : 26/09/2022

Est. Duration of : 2  
Repair

Inspection

Inspection At : SBS TRANSIT PTE LTD (ULU PANDAN) (HQ)  
ULU PANDAN WS, 1 BUSINESS PARK DRIVE, SINGAPORE  
608506.  
SINGAPORE 608506

**Point of Impact / General Description of Damages**

Parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	4,241.00
Revised Amount	:S\$	3,098.00
Check Items (Estimated)	:S\$	1,143.00
Total	:S\$	4,241.00

Lump Sum Repair :S\$

**Total Loss Consideration**

New for Old Value	:S\$
Pre-Accident Value	:S\$
COE / PARF Rebate	:S\$

Salvage Value	:S\$
Margin for Repair	:S\$

**Remarks**

- ( ) The vehicle is repairable at our adjusted amount. We have also confirmed excess and policy coverage. Kindly let us have your authorisation.
- ( ) The vehicle is uneconomical to be repaired, you are advised to invite tender for the wreck.
- ( X ) Other comments : Please note that the preliminary advice amount (Revised & Check Items) stated are subject to consistency check, part prices and labour cost.