Accident Repair Estimate

DENT DATE:

16-Sep-22

BUS NUMBER:

SBS3816U

ACCIDENT TIME:

21:00

BUS MODEL:

DD

ACCIDENT REPORT NUMBER:

AR-2022-2465

DATE OF SURVEY:

26-Sep-22

3RD PARTY CLAIM AGAINST:

GBL1127A

SECTION A:	PARTS & MATERIAL COST	and the same of the same of the same
	Quantity	Total Cost
Part or Item Description		\$952.00
0060 OS NO 4 BODY PANEL		\$858.00
00 OS NO 3 BODY PANEL		\$1,143.00
0107 OS LOWER BODY PILLIAR BR		VIII.
	TOTAL PARTS & MATERIAL COST	\$2,953.00

	ASSESSMENT/REPAIR/SPRAY PAINT (LABOUR COST)	
SECTION B:		\$188.00
To Remove / Replace / Repair Damaged Parts by Workshop		\$800.00
To Bornova / Replace / Repair Damaged Parts by Contractor		\$300.00
To Remove/ Replace/ Repair Damaged Advertisement Panel	TOTAL LABOUR COST	\$1,288.00

	SUMMARY	
SECTION C:		\$4,241.00
	(2)	\$842.62
Total Repair Costs	(1)	\$0.00
Total Downtime (Days)		\$1,182.30
Towing Cost		\$6,265.92
Total Overheads Costs T	OTAL COST	

*Please kindly note that the downtime (days) is just an estimate.
*Please undersign to ocknowledge this repair estimate.

JEFFREY LEONG Senior Foreman Ulu Pandan Workshot Bus Engineding

Surveyor Name & Contact:

Prepared by:

Signature:

1022 Date:

_ Signature :

Date:

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- · Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

CS CamScanner