



# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 1

## ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SKP 2366S

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
<b><u>REPLACEMENT OF PARTS</u></b>				
1	REAR BOOTLID (CONSISTENT)	BENT	1,189.40	1,115.00
1	REAR BOOTLID CENTRE LOGO (CONSISTENT)	NECESSARY	82.50	55.50
1	REAR BOOTLID MAZDA EMBLEM (CONSISTENT)	NECESSARY	50.80	50.80
1	REAR BOOTLID 6 EMBLEM (CONSISTENT)	NECESSARY	51.00	51.00
1	REAR BOOTLID SKYACTIVE EMBLEM (CONSISTENT)	NECESSARY	79.70	79.70
1	REAR BUMPER (CONSISTENT)	BUCKLED	1,313.60	1,231.50
2	REAR BUMPER TOW HOOK COVER@63.40 (CONSISTENT)	SERVICEABLE	126.80	-
1	REAR BUMPER REINFORCEMENT (CONSISTENT)	BENT	601.80	601.80
	LESS 20% DISCOUNT		-699.12	-637.06
			2,796.48	2,548.24
<b><u>SPECIAL NETT ITEMS</u></b>				
1	SET REVERSE SENSORS (SN) (CONSISTENT)	SHORTED	280.00	200.00
			280.00	200.00
<b><u>LABOUR</u></b>				
	SPRAY PAINTING ON BEAM,BUMPER ,BOOTLID.		600.00	400.00
	TO REMOVE AND REPLACE ABOVE PARTS.		600.00	400.00
	TO CHECK WIRING WORKS.		30.00	15.00
	TO REMOVE AND INSTALL REAR BOOTLID.		120.00	50.00
			1,350.00	865.00
<b>GRAND TOTAL</b>			<b>4,426.48</b>	<b>3,613.24</b>
<b>RECOMMENDED COST OF REPAIRS</b>				<b>3,613.24</b>

Report Ref No. CS/ASM22009434/Kqy3m4

KONG SENG CHEONG

Licensed Appraiser

**DISCLAIMER OF LIABILITY TO THIRD PARTIES:-** This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.