



## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
AXA INSURANCE PTE LTD 8 SHENTON WAY #24-01 AXA TOWER SINGAPORE 068811 ATTN: LOW GARNET			Ref: CS/ASM22009434/Kqy3m4 Date: 13/10/2022 Code: ASM	
<b>1. Policy Particulars :- THIRD PARTY CLAIM</b>				
	<b>Insured Veh.</b>	SLW 520C	<b>Veh. Inspected</b>	SKP 2366S
	<b>Policy No.</b>	GA346057	<b>Coverage (\$)</b>	0.00
	<b>Claim No.</b>	S2M04BM9	<b>Excess (\$)</b>	0.00
	<b>Assign From</b>	LOW GARNET	<b>Assign Date</b>	26/09/2022
<b>2. Vehicle Particulars &amp; Condition</b>				
	<b>Make &amp; Model</b>	MAZDA 6 (A)	<b>c.c</b>	1998
	<b>Engine No.</b>	HIDDEN	<b>Year of Reg.</b>	2016
	<b>Chassis No.</b>	JM6GJ1072G0225103	<b>Colour</b>	METALLIC GREY
	<b>Odometer</b>	153395 KM	<b>Steering</b>	IN ORDER
	<b>Brakes</b>	IN ORDER	<b>Modification</b>	STANDARD ALLOY RIM
	<b>General</b>	GOOD		
<b>3. Conditions of Tyres</b>				
		<b>Size</b>	<b>Make</b>	<b>Balance</b>
	<b>R/H Front Tyre</b>	225/55 R17	TOYO	7 mm
	<b>L/H Front Tyre</b>	225/55 R17	TOYO	7 mm
	<b>R/H Rear Tyre</b>	225/55 R17	TOYO	7 mm
	<b>L/H Rear Tyre</b>	225/55 R17	TOYO	7 mm
<b>4. Description of Damages</b>				
	THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION. DAMAGES SEE DETAILS.			
<b>5. General Information</b>				
	<b>Accident Date</b>	22/09/2022	<b>Inspection Date</b>	26/09/2022
	<b>Survey held at</b>	RC AUTO 160 SIN MING DRIVE #06-20 SIN MING AUTOCITY SINGAPORE 575722		
<b>5a. Remarks</b>				
	A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.			
<b>5b. Estimate Days of Repair</b>				
	ESTIMATED NORMAL PERIOD FOR REPAIR:		<b>4 Working Days</b>	