

ASS. REC. BY:

REF:

ASM/22009434/Kq43

C

Kenneth

ASSIGNMENT

From: _____ Date: _____

Estimated Cost: _____

OD/TP/WS/TP RES/OD RES/EVA/INV/MV

To Inspect Vehicle No: _____

at Workshop m/s _____

of _____

Insured: _____

Policy No. _____

Claims No. _____

Sum Insured: _____

Excess: _____

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.

Bal. or Market Value: \$60k

IDAC Accident Report: _____

Consistent? : Yes or No

GIA / PR Seen: _____

Consistent? : Yes or No

Est. Repairs: _____

days

Res.: Yes or No

Lum Sum: _____

20 %

3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: _____

Person Contacted: _____

Vehicle: IN / OUT

Veh No: SKP 23665

Yr Regn: 02, 16

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: Macd9

c.c.

1998

Colour: M. Grey

A/C: Insured / Std / NI / NA

Sp. Reading: 153395

T/Radio: Insured / Std / NI / NA

Eng/No: _____

C/No: JN6GJ1072G8225103

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt or

Brake: Inorder / Jammed / Leaked / Burnt or

Modl: Nil / S/Rlm / STD / Rlm or

Tyre Size: F: 225/55R17

R: _____

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

Rear

R/Bal. 7 mm

R/Bal. 7 mm

L/Bal. 7 mm

L/Bal. 7 mm

D.O.A. 22/9/22

D.O.A. 26/9/2022

Survey held at

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

1

GIA & Est not ready

3/10

3613.24 Cntr Used \$823.24, (9%)
(No Lump Sum)

Date/Time, File Pass to?

1) 12/10 TUNIS

Date/Time, File Return to?

2)

☐

: Prel. Report

☐

: Final Report

Days Of Repair: 4

Resurvey No. of Trip: 2

Survey Fee:

Transportation:

S - RS. \$

Fees

Others

TOTAL

Add Fee:

☐

: Site Insp (\$)

☐

: Interview (\$)

☐

: Tech Invs (\$)

☐

: Weekend (\$)

Report Format:

Smart Claims - TP

Lump Sum / I.B.I. (\$)

3613.24

ESTIMATE RC AUTO

NOT Notified
Resurvey B4 painting

4 days

160 Sin Ming Drive #06-20 Sin Ming Autocity Singapore 575722

Tel : 97619383 Email: rcauto5555@gmail.com

Reg. No. 53199168K

83613.24

SKP 2366 S

Date : 27.09.2022

Quantity	Description/Particular	Unit Price	Amount	
1 PC	REAR BOOTLID 1115		1189	40
1 PC	REAR BOOTLID CENTRE LOGO 55-50		82	50
1 PC	REAR BOOTLID MADZA EMBLEM		50	80
1 PC	REAR BOOTLID 6 EMBLEM		51	00
1 PC	REAR BOOTLID SKYACTIVE EMBLEM		79	70
1PC	REAR BUMPER 1231.50		1313	60
2 PCS	REAR BUMPER TOW HOOK COVER@63.40		126	80
1 PC	REAR BUMPER REINFORCEMENT		601	80
		TOTAL	3495	60
		LESS 20	2796	48
	SPRAY PAINTING ON BEAM,BUMPER ,BOOTLID		600	00
1 SET	REVERSE SENSORS		280	00
	TO REMOVE AND REPLACE ABOVE PARTS		600	00
	TO CHECK WIRING WORKS		30	00
	TO REMOVE AND INSTALL REAR BOOTLID		120	00
	MECHANISM			
			4436	48

Received the above goods in good order and condition

for RC AUTO

Received by

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third Party is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Authorised Signature