

FASTECH AUTO PTE LTD
 1 Kaki Bukit Ave 6 #01-48 Autobay
 Singapore 417883
 Tel No: 67452063/ 67467158 Fax No: 67458520
 Tax Reg No : 200006262D

MS. AD Tong

Not Authorized
 du

26/09/22

2/5 \$ 10,000

6 days.

VEHICLE No: SLD 9489B

1PC	FRONT BUMPER	762.40	Dis	\$985.20	—
1PC	FRONT BUMPER LOWER	480.00	Dis	\$650.00	—
1PC	FRONT BUMPER SIDE RETAINER N/S		buf	\$66.50	—
1SET	FRONT BUMPER CLIPS		net	\$50.00	—
1PC	FRONT BUMPER FOG LAMP N/S	380.50	cre	\$399.50	—
1PC	FRONT BUMPER FOG LAMP COVER N/S	165.40	cur	\$188.90	—
1PC	HEADLAMP N/S LED	1859.40	cre	\$1,959.20	—
1PC	FRONT FENDER N/S		r	\$788.10	X
1PC	FRONT FENDER OUTER PROTECTOR N/S	195.00	Dis	\$388.50	—
1PC	FRONT FENDER INNER SHIELD N/S		11	\$315.10	X
1SET	FRONT FENDER INNER SHIELD CLIPS N/S		11	\$50.00	X
1PC	FRONT DOOR N/S	1015.20	Dis/Buf	\$1,409.20	—
1PC	FRONT DOOR INNER RUBBER N/S	166.00	net	\$188.90	—
1SET	FRONT DOOR FRAME STICKER N/S		net	\$60.00	—
1PC	FRONT DOOR INNER LOCK N/S		11	\$345.80	X
1PC	FRONT DOOR HINGE N/S		11	\$90.00	X
1PC	REAR DOOR N/S	988.50	Dis/Buf	\$1,422.80	—
1PC	REAR DOOR LOWER STICKER N/S		net	\$48.00	—
1PC	REAR DOOR INNER RUBBER N/S	166.00	cur	\$188.50	—
1PC	REAR DOOR INNER LOCK N/S		11	\$345.80	X
1SET	REAR DOOR FRAME BLACK STICKER N/S		net	\$60.00	—
1PC	REAR DOOR HINGE N/S		11	\$90.00	X
1PC	FRONT SHOCK ABSORBER N/S	485.50	Buf	\$655.10	—
1PC	FRONT KNUCKLE ARM N/S	566.20	buf	\$599.20	—
1PC	FRONT KNUCKLE ARM BEARING N/S	262.00	net	\$350.00	—
1PC	FRONT LOWER ARM N/S	481.20	cur	\$588.20	—
1PC	FRONT DRIVE SHAFT N/S		11	\$1,280.30	X
1PC	FRONT STEERING RACK ASSY		su	\$1,988.60	X
1PC	FRONT ENGINE CROSS MEMBER	1500.50	Buf/cur	\$1,545.00	—
1PC	REAR WHEEL HUB BEARING N/S	490.00	Damage	\$650.00	—
1PC	REAR SHOCK ABSORBER N/S		11	\$485.00	X
1PC	REAR FENDER N/S		r	\$998.10	X
1PC	REAR FENDER OUTER PROTECTOR N/S	195.20	grated	\$388.10	—
1PC	REAR BUMPER		su	\$762.00	X
1SET	REAR BUMPER CLIPS		11	\$50.00	X
1PC	FRONT SPORT RIM N/S		waped	\$1,100.00	700 s/w
1PC	REAR SPORT RIM N/S		cur	\$1,100.00	700 s/w
1PC	FRONT TYRE N/S		su	\$250.00	X
1PC	ROCKER PANEL N/S		r	\$845.90	X
1PC	ROCKER PANEL GARNISH N/S	588.20	grated/cur	\$665.10	—
				\$24,390.60	

(202)

TO CHECK WIRING	\$50.00	20
TO DISMANTLE & REFIX REAR REVERSE SENSOR	\$60.00	50
TO SPRAY RUST PROOFING	\$180.00	60
TO CONDUCT WHEEL ALIGNMENT	\$120.00	60
TO DISMANTLE & REPLACED FRONT UNDER CARRIAGE	\$400.00	350
TO DISMANTLE & REPLACED REAR UNDER CARRIAGE	\$350.00	120
TO RESET & REPROGRAMME SYSTEM	11 \$120.00	X
TO DISMANTLE & REFIX BOTH N/S DOOR COMPONENTS	\$180.00	120
LABOUR FOR PANEL BEATING & REPLACED PARTS	\$1,000.00	500
TO PUTTY & SPRAY PAINTING	\$1,600.00	1000
TOTAL	\$28,450.60	

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date:

P-11031-70
20%
8828.36
1400
220
12804.36
202
10004