

SKZ3190Y

TP AXA
VERON

Mercedes Benz. C180

WDD2050402R137602

Front Bumper	} NP Nec	1674	X
Front Bumper Clips.		50(SN)	X
Front Bumper Side Holder RH.		58	X
Headlamp RH.	Cracked	3366.	/
Front RH Fender.	Dented	977.	/
Front RH Fender Lower Shield	} NP Nec	221	X
Front RH Fender Lower Shield Clips		30(SN)	X
Front RH Door Wing Mirror Mounting	M	1075	X
Front RH Door Wing Mirror Cover	Cracked	85	/
Front RH Door Wing Mirror Signal Cap.	NP	189	X
Front RH Wheel Rebr.	Cut	1280 780(SN)	
Front RH Tyre	XHP	300(SN)	X
Front RH Lower Arm.	Best	335	/
Front RH Shock Absorber	XHP	749.	X

SKZ3190Y.

Front RH Knuckle Arm. ^{HP} _{on} 1208 ✕

Front RH Wheel Hub ^{Byrd} _{clw} Bearing. 332 ✓

5095

S.N: 780

4585.50

Panel Beating.

~~800~~ 400

Spray Painting.

~~800~~ 300

Wiring.

~~100~~ 30

To spray buff coat

960

~~150~~ 30

To dismantle front undercarriage

~~350~~ 120

To perform wheel alignment.

~~150~~ 80

14,279.00

Total: 6325.50

L/S: SK

04 Days

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date: