

Accident Toolkit

Sketch plan

Sketch of accident scene

SERVICE ESTIMATE

62018 - C00001 SL: SERVICE SALES - PC

Mr Chan Wan Hong

3 Pine Grove

#05-03

Astor Green

Singapore 597590

GST Reg.No:M28920628X

Inv.No. : B&P 0 Page 1

Inv.date. : 23/09/2022

WIP No. : 42604

Veh.In/Out:

*Tel.No. : Mobile: 81826378

Reg.No. : SLJ5216S

Reg.date : 14/12/2016

Mileage : 0

Chassis No: YV1FS28C0H2429249

Closed by : Michelle Ong Siew Be

Svc Consultant :

Remarks : Mr Chan Wan Hong

Op.No	Description	Mech Qty	Price	Disc%	Pkg	Amount	G
802	TO REPLACE REAR BUMPER, REAR LOWER BUMPER, TOW EYE COVER, BRACKETS, CLIPS, ETC.	0	1700.00	0		1,700.00 S	850/
800	TO BLEND AND SPRAY PAINT ON REAR BUMPER, REAR BUMPER SPOILER, TOW EYE COVER, ETC.	0	2250.00	0		2,250.00 S	750/
280	TO CHECK WIRING INCLUDE RESETTING OF ALL ELECTRICAL MODULES	0	588.00	0		588.00 S	/
	BUMPER RAIL REAR S60 ? x an	1.0 EA	1621.60			1,621.60 S	
	TOW COVER REAR S60 1 mu	1.0 EA	89.80			89.80 S	80.82
	BUMPER BRACKET CTR R ? x an	1.0 EA	167.10			167.10 S	
	BUMPER SPOILER REAR de	1.0 EA	590.40			590.40 S	531.36
	PROTECTING PLATE REA ? x an	1.0 EA	538.40			538.40 S	
	BUMPER BRACKET REAR ? x an	1.0 EA	66.10			66.10 S	
	BUMPER BRACKET REAR ? x an	1.0 EA	66.10			66.10 S	
	BUMPER BRACKET REAR ? x an	1.0 EA	66.10			66.10 S	

Call us Direct

8445 5555

8445 1818

SERVICE ESTIMATE

62018 - C00001
 Mr Chan Wan Hong
 3 Pine Grove
 #05-03
 Astor Green
 Singapore 597590

SL: SERVICE SALES - PC

GST Reg.No:M28920628X

Inv.No. . : B&P 0 Page 2

Inv.date. : 23/09/2022

WIP No. . : 42604

Veh.In/Out:

*Tel.No. . : Mobile: 81826378

Reg.No. . : SLJ5216S

Reg.date . : 14/12/2016

Mileage . : 0

Chassis No: YV1FS28C0H2429249

Closed by : Michelle Ong Siew Be

Svc Consultant :

Remarks : Mr Chan Wan Hong

Op.No	Description	Mech Qty	Price	Disc%	Pkg	Amount	G
	BUMPER BRACKET REAR ? XAN	1.0 EA	66.10			66.10 S	
	PARK SENSOR 29dB 90 ? XAN	4.0 EA	235.60			942.40 S	
	BUMPER INSTALLING MT renew	1.0 EA	101.40			101.40 S	
	BUMPER CLIP XC90 16- renew	10.0 EA	8.80			88.00 S	75.20
	BLIND RIVET 4.0*21 P renew	10.0 EA	5.00			50.00 S	45
	BUMPER CLIP 8x8,5 renew	10.0 EA	8.20			82.00 S	73.80
	BUMPER CLIP GREEN S6 renew	10.0 EA	6.00			60.00 S	54
	EXPANDING NUT XC40 1 renew	10.0 EA	6.70			67.00 S	60.30

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Labour Total 4,538.00
 Parts Total 4,662.50
 Package Total 0.00

Gross Total. 9,200.50

Net..... 9,200.50

GST @ 7.0% 644.04

Total..... 9,844.55

Paid..... 0.00

Please Pay.. 9,844.55

GST: S=StdRated; O=OutOfScope; Z=ZeroRated

Supplementary List

SERVICE ESTIMATE

0 - C00010 SL: CHINA TAIPING INSURANCE (SINGAPORE) CHINA TAIPING INSURANCE (SINGAPORE) PTE LTD 3 ANSON ROAD #16-00, SPRINGLEAF TOWER SINGAPORE 079909	GST Reg.No:M28920628X Inv.No. . : B&P 0 Page 1 Inv.date. : 25/11/2022 WIP No. . : 50620 Veh.In/Out: 17/11/2022 22/11/2022 *Tel.No. . : 63896111 Reg.No. . : SLJ5216S Reg.date .: 14/12/2016 Mileage ..: 116,817 Chassis No: YV1FS28C0H2429249
Closed by : Michelle Ong Siew Be Svc Consultant : ACC Remarks : Mr Chan Wan Hong	

Op.No	Description	Mech Qty	Price	Disc%	Pkg	Amount	G
	BUMPER COVER REAR S6 de✓	1.0 EA	2087.70	10		1,878.93	S

Gross Total.	1,878.93
Net.....	1,878.93
GST @ 7.0%	131.53
Total.....	2,010.46
Paid.....	0.00
Please Pay..	2,010.46

Labour Total	0.00
Parts Total	1,878.93
Package Total	0.00

GST: S=StdRated; O=OutOfScope; Z=ZeroRated