



Mercedes-Benz

Cycle & Carriage  
Industries Pte Limited  
Authorised Dealer  
Company No. 196400367W  
GST Reg No. MR-8500111-X

## ESTIMATE FOR SMS2323B

LONPAC INSURANCE BHD

MOTOR CLAIM DEPARTMENT  
300 BEACH ROAD  
#17-04/07 THE CONCOURSE  
SINGAPORE 199555  
62507388

### Vehicle & Document Information

WIP No **59808**  
Reg No/Reg Date **SMS2323B / 12/11/2019**  
Date In/Mileage **/ 0**  
Chassis No **WDD2573502A0245499**  
Engine No **26492030049708**  
Make/Model **MB/MB CLS 350 COUPE**  
Colour/Trim **029 992 Selenite Gr/ 042 211 Leather Bla**

Account No	Terms	Date/Time Printed	CSE	Operator	
WL001605	Credit	26/09/2022/ 13:14	AQ	305 / Alan Quek Ai Lun	
Description of Goods / Services		Qty	Unit Price	Disc%	Amount

M BPNSUN

POLICY NO/ACC DATE : 1900244827 // 23-09-2022  
DRIVE IN: 26-09-2022 // TP CAR NO: SMY3720A (LONPAC INSURANCE)

DATE IN/DATE SURVEY:  
BY/AUTHORIZED ON :

A BPILAB

USE XENTRY TO CHECK CONTROL UNITS & RESET MEMORY TO  
STANDARD SETTINGS.NETT

A BPILAB

REMOVE & REPAIR FRONT BUMPER

A BPIRES

RESPRAY FRONT BUMPER

0.10 380.00

1440.00

0.07 1000.00

ESTIMATE

**Alan Quek**  
Cycle & Carriage Industries Pte Ltd  
Body Care & Repair Center  
DID: 6771 4377 HP: 9186 5112 Fax: 6872 1272  
Email: alan.quek@cyclecarriage.com.sg

Confirmed & accepted by

7% GST on **Nett 2,820.00**  
**2820.00 197.40**

Authorized signatory and company stamp

**Total Payable 3,017.40**

Validity of this estimate is 14 days from date of quote. This is a computer generated document, no signature is required.

Estimated costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required after repair work has commenced. Occasionally worn or damaged parts are discovered after work has started and needed for repairs or replacement. However, should this occur, we would advise you. Please be informed that a deposit of 50% of the above estimate is payable before commencement of the work. Payment for this may be made in cash, credit card or cheque. You must also agree to pay full amount for renewal of the windscreen in the event of inadvertent breakage in the course of renewing the rubber seal or other repair requiring the removal of the windscreen.



and Mercedes-Benz are trademarks of Mercedes-Benz Group AG

Pandan Loop Service Center  
188 Pandan Loop  
Singapore 128378  
Tel: 6777 8388  
Fax: 6779 5383  
www.mercedes-benz.com.sg