



Date: 23/08/2022  
 Vehicle No: SLP989X  
 Model: TESLA MODEL 3 STANDARD RANGE  
 Chassis: LRW3F7FJ6MC282859-2021  
 Reg.Year: 2021

Third Party Insurer: AIG  
 Third Party Veh No: SGA1002A  
 Date of Accident: 24/09/2022  
 Estimator: TING AN  
 Surveyor:

NO.	SPECIAL NETT	QTY	UNIT S\$	AMOUNT S\$
1	FRONT BUMPER CLIPS	1		<i>na</i> \$60.00 ✓
2	FRONT FENDER INNER SHIELD CLIPS RH	1		<i>na</i> \$50.00 ✓
3	FRONT TYRE RH	1		\$350.00 ↗
4	FRONT DOOR INNER TRIM BOARD CLIPS RH	1		<i>na</i> \$50.00 X
5	REAR DOOR INNER TRIM BOARD CLIPS RH	1		<i>na</i> \$50.00 X
			S/N TOTAL	\$560.00

**LABOUR CHARGES:**

LABOUR CHARGES TO REMOVE, REPLACE, REFIX & READJUST ACCIDENT AREAS & ETC. *600*  
\$1,000.00

LABOUR CHARGES FOR PAINTING & TO SUPPLY PAINT & FURNISHING MATERIALS AT FRONT BUMPER, FRONT FENDER RH, FRONT DOOR RH, REAR DOOR RH & ETC. *800*  
\$1,000.00

LABOUR CHARGES TO REMOVE & REINSTALLED FRONT DOOR INNER MECHANISM & ETC. TO EFFECT REPLACE OF FRONT DOOR RH. *na* \$150.00 X

LABOUR CHARGES TO REMOVE & REINSTALLED REAR DOOR INNER MECHANISM & ETC. TO EFFECT REPLACE OF REAR DOOR RH. *na* \$150.00 X

LABOUR CHARGES TO REMOVE & REPLACE FRONT ABSORBER RH, FRONT LOWER ARM RH, FRONT UPPER ARM RH, FRONT KNUCLLE ARM RH, FRONT WHEEL BEARING HUB RH & ETC. \$350.00 ↗

TO WHEEL ALIGNMENT & BALANCING. \$90.00 *80*

LABOUR CHARGES TO REMOVE & REPLACE FRONT BUMPER PARKING SENSOR & ETC. \$120.00 *60*

TO DIAGNOSIS FAULT CODE & RESET MEMORY. \$150.00 *120*

TO CHECK WIRING & ELECTRICAL SYSTEM. \$120.00 *20*

**LABOUR TOTAL** **\$3,130.00**

TING AN **TOTAL** **\$10,373.17**

**Head office**

6 Kung Chong Road Singapore 159143  
 Tel: (+65) 6472 1313 | Fax: (+65) 6472 2112

**Branch**

9A Serangoon North Ave 5 Singapore 554500  
 Tel: (+65) 6484 9919 | Fax: (+65) 6481 1993

**Branch (Motor Insurance Claims)**

Blk 10 Ang Mo Kio Ind. Park 2A #01-05 Singapore 568047  
 Tel: (+65) 6481 1522 | Fax: (+65) 6481 1011

