

Date: 23/08/2022  
 Vehicle No: SLP989X  
 Model: TESLA MODEL 3 STANDARD RANGE  
 Chassis: LRW3F7FJ6MC282859-2021  
 Reg. Year: 2021

*Not authorized*  
*Pinny B4 pain*  
*6 days*

Third Party Insurer: AIG  
 Third Party Veh No: SGA1002A  
 Date of Accident: 24/09/2022  
 Estimator: TING AN  
 Surveyor:

86401.79

**ESTIMATE**

NO.	DESCRIPTION	QTY	UNIT S\$	AMOUNT S\$	
1	FRONT HEADLAMP RH	1	CMA	\$1,308.41	✓
2	FRONT HEADLAMP LOWER BRACKET RH	1		PLC \$7.48	X
3	FRONT BUMPER	1		Bu \$631.00	✓
4	FRONT BUMPER SIDE BRACKET RH	1		DII \$9.35	✓
5	FRONT BUMPER UPPER BRACKET RH	1		PL \$1.87	X
6	FRONT BUMPER PARKING SENSOR	1		SL \$163.55	X
7	FRONT BUMPER PARKING SENSOR BRACKET	1		SL \$4.67	X
8	FRONT FENDER RH	1		PL \$448.60	✓
9	FRONT FENDER INNER SHIELD RH	1		CMA \$116.82	✓
10	FRONT FENDER SIDE REPEATER RH	1		PL \$196.26	✓
11	FRONT RIM RH	1		PL \$505.00	✓
12	FRONT RIM COVER RH	1		PL/PL \$32.71	✓
13	FRONT ABSORBER RH	1		PL \$429.91	X
14	FRONT UPPER ARM RH	1		DII \$121.50	X
15	FRONT LOWER ARM RH	1		PL \$224.30	X
16	FRONT KNUCKLE ARM RH	1		PL \$420.56	X
17	FRONT WHEEL BEARING HUB RH	1		PL \$233.64	X
18	FRONT DOOR RH	1		R \$1,009.35	X
19	FRONT DOOR HANDLE RH	1		COT \$214.95	✓
20	FRONT DOOR WEATHERSTRIP RH	1		PL \$88.79	X
21	FRONT DOOR UPPER HINGE RH	1		R \$74.77	X
22	FRONT DOOR LOWER HINGE RH	1		R \$74.77	X
23	FRONT DOOR CHECKER RH	1		PL \$65.42	X
24	REAR DOOR RH	1		R \$953.27	X
25	REAR DOOR WEATHERSTRIP RH	1		PL \$88.79	X

SUB TOTAL	\$7,425.74
LESS 10%	-\$742.57
<b>PARTS TOTAL</b>	<b>\$6,683.17</b>

**LKK Auto Consultants** hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer  
 Signature: \_\_\_\_\_

**Head office**  
 6 Kung Chong Road Singapore 159143  
 Tel: (+65) 6472 1313 | Fax: (+65) 6472 2112

**Branch**  
 9A Serangoon North Ave 5 Singapore 554600  
 Tel: (+65) 6484 9919 | Fax: (+65) 6481 1993

**Branch (Motor Insurance Claims)**  
 Blk 10 Ang Mo Kio Ind. Park 2A #01-05 Singapore 568047  
 Tel: (+65) 6481 1522 | Fax: (+65) 6481 1011



Date: 23/08/2022  
 Vehicle No: SLP989X  
 Model: TESLA MODEL 3 STANDARD RANGE  
 Chassis: LRW3F7FJ6MC282859-2021  
 Reg.Year: 2021

Third Party Insurer: AIG  
 Third Party Veh No: SGA1002A  
 Date of Accident: 24/09/2022  
 Estimator: TING AN  
 Surveyor:

NO.	SPECIAL NETT	QTY	UNIT S\$	AMOUNT S\$
1	FRONT BUMPER CLIPS	1		<i>nn</i> \$60.00
2	FRONT FENDER INNER SHIELD CLIPS RH	1		<i>nn</i> \$50.00
3	FRONT TYRE RH	1	<i>3155n</i>	<i>nn</i> \$350.00
4	FRONT DOOR INNER TRIM BOARD CLIPS RH	1		<i>nn</i> \$50.00
5	REAR DOOR INNER TRIM BOARD CLIPS RH	1		<i>nn</i> \$50.00
			S/N TOTAL	\$560.00

**LABOUR CHARGES:**

LABOUR CHARGES TO REMOVE, REPLACE, REFIX & READJUST ACCIDENT AREAS & ETC.

*600*  
\$1,000.00

LABOUR CHARGES FOR PAINTING & TO SUPPLY PAINT & FURNISHING MATERIALS AT FRONT BUMPER, FRONT FENDER RH, FRONT DOOR RH, REAR DOOR RH & ETC.

*800*  
\$1,000.00

LABOUR CHARGES TO REMOVE & REINSTALLED FRONT DOOR INNER MECHANISM & ETC. TO EFFECT REPLACE OF FRONT DOOR RH.

*nn* \$150.00 X

LABOUR CHARGES TO REMOVE & REINSTALLED REAR DOOR INNER MECHANISM & ETC. TO EFFECT REPLACE OF REAR DOOR RH.

*nn* \$150.00 X

LABOUR CHARGES TO REMOVE & REPLACE FRONT ABSORBER RH, FRONT LOWER ARM RH, FRONT UPPER ARM RH, FRONT KNUCLLE ARM RH, FRONT WHEEL BEARING HUB RH & ETC.

\$350.00 *200*

TO WHEEL ALIGNMENT & BALANCING.

\$90.00 *80*

LABOUR CHARGES TO REMOVE & REPLACE FRONT BUMPER PARKING SENSOR & ETC.

\$120.00 *60*

TO DIAGNOSIS FAULT CODE & RESET MEMORY.

\$150.00 *120*

TO CHECK WIRING & ELECTRICAL SYSTEM.

\$120.00 *20*

**LABOUR TOTAL** \$3,130.00