

LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
	MS FIRST CAPITAL INSURANCE LTD		Ref:	CS/FCI22009464/Uny3q2
	36 ROBINSON ROAD #16-01 CITY HOUSESINGAPORE 068877		Date:	06/10/2022
			Code:	FCI2
1.	Policy Particulars :- THIRD PARTY CLAIM			
	Insured Veh.	GBG 8363P	Veh. Inspected	SLU 7462B
	Policy No.		Coverage (\$)	0.00
	Claim No.	D22003000MFCV	Excess (\$)	0.00
	Assign From	HARMINDER KAUR	Assign Date	26/09/2022
2. Vehicle Particulars & Condition				
	Make & Model	MERCEDES BENZ C180 (A)	c.c	1595
	Engine No.	HIDDEN	Year of Reg.	2017
	Chassis No.	WDD2050402R336521	Colour	BLACK
	Odometer	86341 KM	Steering	IN ORDER
	Brakes	IN ORDER	Modification	SPORTS RIM
	General	GOOD		
3. Conditions of Tyres				
		Size	Make	Balance
	R/H Front Tyre	225/50 R17	MICHELIN	7 mm
	L/H Front Tyre	225/50 R17	MICHELIN	7 mm
	R/H Rear Tyre	225/50 R17	MICHELIN	7 mm
	L/H Rear Tyre	225/50 R17	MICHELIN	7 mm
4.	Description of Damages			
	THE VEHICLE SUSTAINED DAMAGES AT THE O/S FRONT PORTION.			
	DAMAGES SEE DETAILS.			
5.	General Information			
	Accident Date	24/09/2022	Inspection Date	26/09/2022
	Survey held at	39 Woodlands Close, MEGA@Woodlands #01-24		
	Repairer	airer NINETEEN AUTOWERKS PTE. LTD.		
5a.	Remarks			
	A)DAMAGES CONSISTENT TO ACCIDENT REPORT. B)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. C)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.			
5b.	Estimate Days of Repair			
	ESTIMATED NORMAL PERIOD FOR REPAIR: 4 Working Days			