

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com; cs-a@lkkauto.com; admin-a@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CC6/AIG22009467/AYA3Q2**Date:** 01/03/2023REFERENCE

Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd.	Policy No:	2100344734
Claimant Vehicle No :	SMT9552E	Insured Vehicle No :	SFB9638U
Date of Loss:	19/09/2022	Nature of Claim:	TP
		Claim No:	3534058636SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SMT9552E	Engine No:	L15B4024636
Make & Model:	HONDA VEZEL, 1.5 X A (A)	Chassis No:	RU11104634
Reg. Date:	06/01/2016 (Man. Year: 2015)	Odometer:	116136 km
Colour:	Blue		
Engine Capacity:	1496 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	215/55 R17	Rear Tyre Size:	215/55 R17
Front Left Side:	Michelin 6 mm	Rear Left Side:	Michelin 6 mm
Front Right Side:	Michelin 6 mm	Rear Right Side:	Michelin 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	10,195.60	7,278.96	2,916.64	28.61
Miscellaneous Items	0.00	0.00	0.00	
Labour	4,080.00	2,950.00	1,130.00	27.70
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	14,275.60	10,228.96	4,046.64	28.35
Approved Total (Overridden) (S\$)		8,150.00		
(S\$)	14,275.60	8,150.00	6,125.60	42.91
+ GST 7.00/7.00% (S\$)	999.29	570.50	428.79	42.91
Nett Amount (S\$)	15,274.89	8,720.50	6,554.39	42.91
+ Car Rental (9.0 x S\$100.00/day) (S\$)		900.00		
+ Doc/Search Fee (S\$)		2.00		
Nett Liability (S\$)		9,622.50		

INSPECTION

Date of Assignment:	29/09/2022	
Date Inspected:	29/09/2022	Inspected At: Modern Automotive Pte Ltd (HQ) Blk 3023A Ubi Road 1, #01-61 & #01-58 Singapore 408717
Estimated Period of Repair:	9.0 days	

Adjuster: ADRIAN LING**Manager:** Ezlyna

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR BUMPER	Deformed	821.40 FL	*821.40 FL
2	2		*REAR BUMPER SIDE HOLDER -LH & RH	Necessary	56.00 FL	*56.00 FL
3	2		*REAR BUMPER REFLECTOR -LH & RH	Not Necessary	282.20 FL	*- FL
4	2		*REAR BUMPER SIDE APRON -LH & RH	Repair	390.00 FL	*- FL
5	1		*REAR END PANEL	Dented	585.40 FL	*585.40 FL
6	1		*REAR END PANEL TOP GARNISH	Deformed	98.40 FL	*98.40 FL
7	1		*REAR END PANEL ANTENNA SENSOR	Not Necessary	90.90 FL	*- FL
8	1		*REAR END PANEL BUZZER	Cracked	85.20 FL	*85.20 FL
9	2		*TAILLAMP -LH & RH	Cut	949.20 FL	*949.20 FL
10	1		*TAILGATE	Distorted	1,100.00 FL	*1,100.00 FL
11	1		*TAILGATE LOCK	Damaged	182.50 FL	*182.50 FL
12	1		*TAILGATE WEATHERSTRIPE	Cut	188.90 FL	*188.90 FL
13	2		*TAILGATE REFLECTOR -LH & RH	Cut	826.40 FL	*826.40 FL
14	1		*TAILGATE OUTER GARNISH	Not Necessary	325.00 FL	*- FL
15	1		*TAILGATE INNER TRIM BOARD	Deformed	285.60 FL	*285.60 FL
16	1		*TAILGATE GLASS MOULDING	Necessary	145.10 FL	*145.10 FL
17	1		*HONDA LOGO	Not Necessary	45.60 FL	*- FL
18	1		*VEZEL WORDING	Necessary	52.90 FL	*52.90 FL
19	2		*REAR FENDER INNER TRIM BOARD -LH & RH	Not Necessary	710.40 FL	*- FL
20	2		*REAR FENDER ARC GARNISH -LH & RH	Deformed	392.00 FL	*392.00 FL
21	1		*SPARE TYRE PANEL	Buckled	1,130.00 FL	*1,130.00 FL
22	1		*SPARE TYRE PANEL TOP BOARD	Deformed	306.60 FL	*306.60 FL
23	1		*SPARE TYRE PANEL UNDERCOVER	Deformed	245.20 FL	*245.20 FL
24	1		*TOOLS TRAY SPONGE	Deformed	285.40 FL	*285.40 FL
25	1		*REAR EXHAUST PIPE	Not Necessary	598.60 FL	*- FL
26	1		*REAR EXHAUST PIPE MOUNTING	Not Necessary	34.90 FL	*- FL
27	1		*REAR EXHAUST PIPE GASKET	Not Necessary	32.40 FL	*- FL
28	1		*REAR EXHAUST PIPE HEAT SHIELD	Not Necessary	98.30 FL	*- FL
29	1		*REAR NUMBER PLATE	Not Necessary	30.00 FS	*- FS
30	1		*REAR NUMBER PLATE HOLDER	Not Necessary	30.00 FS	*- FS
31	1		*SET REAR BUMPER CLIPS	Necessary	30.00 FS	*30.00 FS
32	2		*REAR BUMPER REFLECTOR CHROME MOULDING -LH& RH	Necessary	200.00 FS	*150.00 FS
33	1		*REAR BUMPER LOWER CHROME MOULDING	Deformed	280.00 FS	*250.00 FS
34	1		*REVERSE SENSOR	Damaged	280.00 FS	*200.00 FS
35	1		*SET REAR END PANEL TOP GARNISH CLIPS	Necessary	20.00 FS	*20.00 FS
36	1		*REAR END PANEL TOP GARNISH CHROME PLATE	Necessary	250.00 FS	*200.00 FS
37	1		*REAR END PANEL SEALANT	Necessary	60.00 FS	*60.00 FS
38	1		*SET TAILGATE OUTER GARNISH CLIPS	Not Necessary	20.00 FS	*- FS
39	1		*SET TAILGATE INNER TRIM BOARD CLIPS	Necessary	30.00 FS	*30.00 FS
40	1		*TAILGATE GLASS SEALANT	Necessary	60.00 FS	*60.00 FS
41	1		*REAR CAMERA	Not Necessary	480.00 FS	*- FS
42	1		*SET REAR FENDER INNER TRIM BOARD CLIPS	Not Necessary	60.00 FS	*- FS
43	1		*SET REAR FENDER ARC GARNISH CLIPS	Necessary	60.00 FS	*60.00 FS
44	1		*SET SPARE TYRE PANEL UNDERCOVER CLIPS	Necessary	30.00 FS	*30.00 FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$)	12,264.50	8,826.20
- List Item Discount on L Items 20.00/20.00% (\$\$)	2,068.90	1,547.24
Total Parts (\$\$)	10,195.60	7,278.96

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO KNOCKING & PULL OUT REAR DOOR PORTION & RENEW ABOVE PARTS	New	1,500.00	1,300.00
2	TO PUTTY 7 SPRAY UP PAINT WORKS	New	1,400.00	1,000.00
3	TO CHECK WIRING	New	50.00	30.00
4	TO REMOVE REVERSE SENSOR	New	100.00	50.00
5	TO REMOVE REAR CAMERA	New	100.00	50.00
6	TO REMOVE UPHOLSTERY AND REAR SEAT	New	300.00	220.00
7	TO REMOVE TAILGATE GLASS	New	180.00	120.00
8	TO TRANSFER TAILGATE FITTINGS	New	150.00	80.00
9	TO REMOVE EXHAUST PIPE	New	150.00	0.00
10	TO SPRAY TUFF COAT	New	150.00	100.00
Gross Labour Cost (S\$)			4,080.00	2,950.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >