



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
CHINA TAIPING INSURANCE (S) PTE LTD 3 ANSON ROAD #16-00 SPRINGLEAF TOWERSINGAPORE 079909			Ref: CS3/CTI21010195/Rqy3e2-1 Date: 16/01/2023 Code: CTI	
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	SMH 6530B	Veh. Inspected	SMA 287E	
Policy No.	DMPCSNW00045602100	Coverage (\$)	0.00	
Claim No.	SNM21D205373/C02/TOHHS	Excess (\$)	0.00	
Assign From	ALFRED TOH	Assign Date	21/09/2022	
2. Vehicle Particulars & Condition				
Make & Model	B.M.W. 116D 5DR HATCHBACK DSC	c.c	1496	
Engine No.	HIDDEN	Year of Reg.	2015	
Chassis No.	WBA1V720005C06725	Colour	RED	
Odometer	72779 KM	Steering	IN ORDER	
Brakes	IN ORDER	Modification	SPORTS RIM	
General	FAIR			
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre	225/40 R18	YOKOHAMA	6 mm	
L/H Front Tyre	225/40 R18	YOKOHAMA	6 mm	
R/H Rear Tyre	225/40 R18	YOKOHAMA	6 mm	
L/H Rear Tyre	225/40 R18	YOKOHAMA	6 mm	
4. Description of Damages				
THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION. DAMAGES SEE DETAILS.				
5. General Information				
Accident Date	21/09/2021	Inspection Date	04/10/2021	
Survey held at	ALPHA CAR SERVICES PTE LTD BLK C, KAKI BUKIT AVE 6 #01-59 KAKI BUKIT AUTOBAY SINGAPORE 417883			
5a. Remarks				
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
5b. Estimate Days of Repair				
ESTIMATED NORMAL PERIOD FOR REPAIR:			4 Working Days	