



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile			
AXA INSURANCE PTE LTD		Ref:	CC4/ASM22009472/Kpa3q2
8 SHENTON WAY #24-01		Date:	10/10/2022
AXA TOWERSINGAPORE 068811		Code:	ASM
ATTN:CYNTHIA			
1. Policy Particulars :- THIRD PARTY CLAIM			
Insured Veh.	SH 9052Z	Veh. Inspected	SMZ 2835D
Policy No.	P2465679	Coverage (\$)	0.00
Claim No.	S2M04BL9	Excess (\$)	0.00
Assign From		Assign Date	23/09/2022
2. Vehicle Particulars & Condition			
Make & Model	MERCEDES BENZ GLB 180 (A)	c.c	1332
Engine No.	HIDDEN	Year of Reg.	2021
Chassis No.	W1N2476842W100445	Colour	WHITE
Odometer	34556 KM	Steering	IN ORDER
Brakes	IN ORDER	Modification	STANDARD ALLOY RIM
General	GOOD		
3. Conditions of Tyres			
	Size	Make	Balance
R/H Front Tyre	235/50 R19	CONTINENTAL	7 mm
L/H Front Tyre	235/50 R19	CONTINENTAL	7 mm
R/H Rear Tyre	235/50 R19	CONTINENTAL	7 mm
L/H Rear Tyre	235/50 R19	CONTINENTAL	7 mm
4. Description of Damages			
THE VEHICLE SUSTAINED DAMAGES AT THE O/S FRONT PORTION. DAMAGES SEE DETAILS.			
5. General Information			
Accident Date	19/09/2022	Inspection Date	26/09/2022
Survey held at	TONG LUCK AUTO PL 160 SIN MING DRIVE #07-01/06 SIN MING AUTOCITY SINGAPORE 575722		
5a. Remarks			
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.			
5b. Estimate Days of Repair			
ESTIMATED NORMAL PERIOD FOR REPAIR:		2 Working Days	