



TONG LUCK AUTO PTE LTD

160 SIN MING DRIVE #07-01/06 SIN MING AUTOCITY, SINGAPORE 575722

Tel: 6250 0088 Fax: 6250 5545

Email: operation@tlauto.com.sg

GST No: 201700521W UEN No: 201700521W

PAGE: 1

M/S : DAIMLER FLEET MANAGEMENT S'PORE PTE LTD
1 GATEWAY DRIVE
#15-08 WESTGATE TOWER
SINGAPORE 608531

TEL : 6849 8118
ATTN : ACCOUNTS DEPT

FAX :

*Not Authorised
Running By painting
2 days*

ESTIMATE

NO : QUOT202209-000038(00)
DATE : 22/09/2022
POLICY NO : 999995580
VEH REG NO : SMZ2835D
MAKE/MODEL : MERCEDES BENZ GLB 180
AMG LINE
CHASSIS NO : W1N2476842W100445
ENGINE NO : 28291480493339
REG. DATE : 2020

YOUR REF NO : SH9052Z
CLAIM TYPE : THIRD PARTY
TP INS. CO. : AXA INSURANCE SINGAPORE PTE LTD
ACCIDENT DATE : 19/09/2022
TP VEH REG NO : SH9052Z

Estimate Repair Cost to Vehicle No : SMZ2835D

Description	Quantity	Unit Price	Amount
		S\$	S\$
NET PRICE			
1 Front bumper	1	1,578.00	1,578.00
2 Front bumper outer garnish	1	135.00	135.00
3 Front bumper side retainer RH	1	55.00	55.00
4 Front bumper sensor RH	1	215.00	215.00
5 Headlamp RH	1	3,480.00	3,480.00
6 Front wheel arch panel RH	1	250.00	250.00
			5,713.00
		Less 10%	571.30
			5,141.70
LABOUR			
7 To check and rectify wiring system	1	80.00	80.00
8 To panel beat front bumper, including replacement of parts and align where necessary, to refit and adjust the same	1	650.00	650.00
9 To putty and spray paint on affected areas	1	800.00	800.00
10 To apply rust-proofing on replaced and repaired panels	1	150.00	150.00
			1,680.00
		TOTAL	S\$ 6,821.70
		ADD GST @ 7%	477.52
		GRAND TOTAL	S\$ 7,299.22

SINGAPORE DOLLAR SEVEN THOUSAND TWO HUNDRED NINETY-NINE AND CENTS TWENTY-TWO ONLY

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

FOR TONG LUCK AUTO PTE LTD