



友尼摩多公司 UNIMOTOR COMPANY

一號加基武吉六道一樓門牌九十四號 新加坡郵區四一七八八三
AUTOBAY @ KAKI BUKIT

No. 1 KAKI BUKIT AVE 6 #01-94 SINGAPORE 417883
TELEPHONE: 6748 2795 FAX: 6747 2373

Registration No.: 203165/00D

GDH2232001917

LKK

DATE: 14/10/2022 OUR REF: UAPL1554
REPAIR ESTIMATE YOU THE TOYOTA HIACE NO: PC8305M
1 FRONT L/H DOOR WIND MIRROR ASSY *new*
1 FRONT L/H FENDER WIND MIRROR ASSY *ut*
1 FRONT BUMPER FACE *ut*
1 FRONT BUMPER L/H FOG LAMP COVER *new*
1 FRONT BUMPER L/H SIDE RETAINER *new*
1 SET FRONT BUMPER CLIPS *new*
1 FRONT BUMPER REINFORCEMENT *new*
1 FRONT L/H HEADLAMP ASSY *new*
1 FRONT L/H STEP PANEL ASSY *new*
1 FRONT L/H STEP PANEL GARNISH *new*
1 FRONT L/H CABLE SOCKET HOLDER *new*

LESS 25 %.....

TP Ergo.

Xmas Chu

\$	1,225.40	✓
\$	632.20	✓
\$	855.20	589.
\$	86.00	X
\$	139.60	X
\$	55.00	30
\$	441.60	X
\$	1,850.50	X
\$	362.30	X
\$	155.60	X
\$	115.20	X
\$	5,918.60	
\$	1,479.65	
\$	<u>4,438.95</u>	

242660
1857.45

LABOUR CHARGES:-

TO DISM/REWIRE DAMAGED SOCKET HOLDER, HEADLAMP

TO PANEL BEAT DAMAGED PORTION AND RENEW PARTS

TO PUTTY AND RESPRAY DAMAGED DOOR, STEP PANEL, DOOR PILLAR

TO SPRAY UNDERCOATING IN REPAIR

\$	180.00	30
\$	900.00	400
\$	800.00	200
\$	120.00	30
\$	<u>6,438.95</u>	

Total: 2517.45

L/S: 2K

2u

03 Days

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: