



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
HSBC LIFE (SINGAPORE) PTE LTD 10 MARINA BOULEVARD #48-01 MARINA BAY FINANCIAL CENTRE TOWER 2SINGAPORE 018983 ATTN:CHEN XINYOU			Ref: CC4/ASM22009476/Apa3q2 Date: 09/06/2023 Code: HSB	
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	SLJ 7747M	Veh. Inspected	SKR 1531C	
Policy No.	GA519724	Coverage (\$)	0.00	
Claim No.	S2M04BK6	Excess (\$)	0.00	
Assign From		Assign Date	26/09/2022	
2. Vehicle Particulars & Condition				
Make & Model	HONDA FIT SHUTTLE	c.c	1497	
Engine No.	HIDDEN	Year of Reg.	2015	
Chassis No.	GG73202472	Colour	SILVER	
Odometer	267380 KM	Steering	IN ORDER	
Brakes	IN ORDER	Modification	SPORTS RIM	
General	GOOD			
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre	195/60 R15	FALKEN	6 mm	
L/H Front Tyre	195/60 R15	FALKEN	6 mm	
R/H Rear Tyre	195/60 R15	FALKEN	6 mm	
L/H Rear Tyre	195/60 R15	FALKEN	6 mm	
4. Description of Damages				
THE VEHICLE SUSTAINED DAMAGES AT THE O/S BODY & UNDERCARRIAGE. DAMAGES SEE DETAILS.				
5. General Information				
Accident Date	22/09/2022	Inspection Date	26/09/2022	
Survey held at	ADVANCE AUTO GARAGE 23 KAKI BUKIT AVENUE 4, #04-01 VICOM KAKI BUKIT INSPECTION CENTER, SINGAPORE 415933.			
5a. Remarks				
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
5b. Estimate Days of Repair				
ESTIMATED NORMAL PERIOD FOR REPAIR:			6 Working Days	