

SKRISBIC

TP AXA.

Honda Fit Shuttle.

Xmas by Sept 22.

GG73202472

Front Bumper.	torn	695.20 ✓
Front Bumper Clips.	Nec	30(SN) ✓
Front Bumper Side Holder RH.	Nec	38.40 X.
Front RH Fender.	Distorted	598.40 ✓
Front RH Fender Inner Shield.	Delam	189.50 ✓
Front RH Fender Inner Shield Clips.	Nec	30(SN) ✓
Front RH Fender Glass Garnish	Nec	68.20 +
Front RH Fender Glass Sealant.	Nec	40(SN) ✓
Headlamp RH.	Cracked.	989.40 ✓
Front RH Door	Dented	1154.20 ✓
Front RH Door Weatherstripe.	Nec	214.90 X.
Front RH Door Black Tape.	Nec	60(SN) ✓

SKR 1531 C.

Front RH Wheel Rlm.	at	850(SN) 480(SN)
Front RH Tyre.	Not Nec	280(SN) X
Front RH Lower Arm.	Bent.	391.40 ✓
Front RH Shock Absorber.	Best	349.50 ✓
Front RH Knuckle Arm.	Damaged	448.40 ✓
Front RH Wheel Hub c/w Bearing.	Good	299.20 ✓
Front RH Anti Roll Bar Linkage.	Not nec	114.90 X

5715.20

4092.16

S.N 640

SKR 1531C.

Panel Bending

~~1000~~ 700

Spray Painting -

~~1000~~ 600

Wiring.

~~50~~ 30

To apply 2nd coat.

~~150~~ 60

To transfer front door fittings.

~~150~~ 80

To dismantle front undercarriage.

~~350~~ 220

To perform wheel alignment.

~~150~~ 80

1770

total: 6502.16.

L/S: 5-2K.

06 Days

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: