

萬 汽 車 服 務

MILLION AUTO SERVICE

No. 4 Penjuru Place #01-12, 2.8 Penjuru Tech Hub, Singapore 608782
 Website: <http://www.millionauto.com> Email: wendy@millionauto.com
 Tel: 6567 0817, 6264 9091 Fax: 6791 4716
 Reg No: 317413/00-K GST Reg No: M90363176A

Vehicle No : GBB3480T

Model : NISSAN CABSTAR

Chassis No : JN1SC2F24Z0800681

Year : 2008

REPAIR ESTIMATE

S/N.	PARTS REPLACEMENT - LIST ITEM	Qty	Unit Price (\$)	Price (\$)	
1	FRONT BUMPER ✓ CRU	1	\$ 1,031.00	\$ 1,031.00	675 ✓
2	FRONT CORNER PANEL RH ✓ DD	1	\$ 471.60	\$ 471.60	389 ✓
3	FRONT DOOR RH ✓ DD	1	\$ 1,590.50	\$ 1,590.50	✓
4	FRONT DOOR SIGNAL LAMP RH ✓ CUT	1	\$ 106.00	\$ 106.00	✓
5	FRONT DOOR INEER TRIMBOARD RH X NN	1	\$ 753.50	\$ 753.50	
6	FRONT DOOR HINGE RH X NN	2	\$ 55.00	\$ 110.00	
7	FRONT DOOR CHECKER RH X NN	1	\$ 75.90	\$ 75.90	
8	FRONT DOOR WEATHERSTRIP RH X NN	1	\$ 234.70	\$ 234.70	
9	FRONT DOOR LOCK RH X NN	1	\$ 338.00	\$ 338.00	
10	FRONT DOOR WINDOW REGULATOR RH X NN	1	\$ 127.10	\$ 127.10	
11	FRONT DOOR STEP GARNISH RH X NN	1	\$ 163.10	\$ 163.10	
12	FRONT SIDE MIRROR PANEL RH X NN	1	\$ 127.60	\$ 127.60	
13	SIDE MIRROR RH X NN	1	\$ 224.50	\$ 224.50	
14	HEADLAMP RH ✓ BR	1	\$ 559.10	\$ 559.10	473 ✓
15	HEADLAMP LOWER GARNISH RH ✓ CRU	1	\$ 86.50	\$ 86.50	✓
				\$ 5,999.10	3320
Less 10%				\$ 599.10	-10%
Sub Total :				\$ 5,391.90	2988

PARTS REPLACEMENT -SPECIALNETT ITEMS

1	FRONT DOOR INNER TRIMBOARD CLIPS X NN	\$ 30.00	
2	FRONT DOOR ROV STICKER ✓ NEC	\$ 30.00	✓
Sub Total :		\$ 60.00	30

LABOUR AND MISCELLANEOUS CHARGES

1	LABOUR FOR PANEL BEATING, CUT, WELD, STRAIGHTEN AFFECTED AREA AND REPLACE DAMAGE PARTS	\$ 1,000.00	400
2	TO PUTTY AND SPRAY PAINTING TO AFFECTED AREA	\$ 900.00	400
3	TO APPLY ANTI RUST PROOFING ON AFFECTED AREA	\$ 80.00	30
4	TO CHECK WIRING AND LIGHTING FUNCTION	\$ 80.00	30
5	TO REMOVE AND TRANSFER DOOR MECHANISM	\$ 100.00	50

Steve (LKK)
 22/07/22, 1.00pm
 Without Prejudice
 L/S
 Resurvey After Spray
 4 days

Sub Total :	\$ 2,160.00	910
Grand Total :	\$7,611.90	3928

L/S - 3142.40
 = 3150