

55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

ESTIMATE : ACCIDENT REPAIRS
WORKSHOP : UBI ROAD 1
CONTACT NO : 6366 2323
FAX NO : 6841 1183
REFERENCE : PA/OD/0826/2022/EQ
DATE : 23-Sep-22
WIP : 43124

VEHICLE IN WORKSHOP. KINDLY ARRANGE FOR SURVEY ON 26/09/2022

AIG ASIA PACIFIC INSURANCE PTE LTD

78 SHENTON WAY

#07-16 AIG BUILDING

SINGAPORE 079120

Attn: Motor Claims Dept

Tel: 6880 4602 - Fax: 6880 4838

Hi Adrian

14 days exclude 2 Sundays

Johnny Boo 30 Nov 22

OWNER'S NAME : MR RAJIV BHANDARI
ADDRESS : BLK 481 YIO CHU KANG ROAD
#03-12
SINGAPORE 787056
TELEPHONE : HP +65 91251765
TYPE OF CLAIM : OWN DAMAGE CLAIM
POLICY NO : 2070153937
VEHICLE NO : **SJN 7516 R**
MODEL CODE : AUDI A4 2.0 TFSI S-TRONIC
MODEL YEAR : 30/10/2020
ENGINE NO : DEM 025385
CHASSIS NO : WAUZZZF47MN001180
MILEAGE : -
DATE IN : -
ESTIMATED BY : JOHNNY BOO / ALLAN WU
ACCIDENT DATE : 22-Sep-22
PLACE OF ACCIDENT : 262D HDB SENGKANG EASTWAY, INSIDE THE CARPARK
BESIDE BLOCK 261A

55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

ESTIMATED LABOUR CHARGES FOR ACCIDENT VEHICLE SJN 7516 R

S/N	NATURE OF JOBS		ESTIMATED CHARGES		SURVEYOR'S RECOMMENDATIONS
1	TO REMOVE, CHECK AND TRANSFER FRONT WIRE HARNESS FOR HEADLIGHTS, HORNS, OUTSIDE TEMPERATURE SENSOR, HEADLIGHT WASHER ASSY AND FRONT PARKING AID.	S/N \$	480.00	\$	480.00
2	TO REMOVE AND TRANSFER BOTH HEADLIGHT'S CONTROL UNIT AND POWER MODULE.	S/N \$	700.00	\$	250.00
3	TO REMOVE AND RENEW AIRCON CONDENSER, CHARGE AIR COOLER AND RADIATOR. CHECK ELECTRICAL FANS AND CONTROL UNIT. PRESSURISE COOLING SYSTEM.	S/N \$	1,400.00	\$	1,400.00
4	TO CARRY OUT VACUUM AND REGAS FOR R1234.	S/N \$	1,200.00	\$	1,200.00
5	TO REMOVE AND REINSTALL BOTH FRONT DOOR PANEL TRIM. TO REMOVE AND REINSTALL BOTH WING MIRROR ASSY TO FACILITATE RESPRAY OF BOTH FRONT DOOR.	S/N \$	560.00	na	
TOTAL LABOUR CHARGES		:	\$ 4,340.00	\$	3,330.00

55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

ESTIMATED LABOUR CHARGES FOR ACCIDENT VEHICLE SJN 7516 R

S/N	NATURE OF JOBS		ESTIMATED CHARGES	SURVEYOR'S RECOMMENDATIONS
		<i>c/f</i>		\$ 3,330.00
6	TO DISMANTLE AND RENEW FRONT BUMPER, BONNET, BOTH FRONT FENDER AND BOTH HEADLIGHT. TO RENEW FRONT LOCK CARRIER AND ALIGN TO POSITION. RE- ORGANIZE CRASH MANAGEMENT COMPONENTS. REINSTALL ALL PARTS REMOVED. <i>(2 ltr Lock carrier x 3 days)</i>	\$	5,600.00	\$ 3,000.00
7	TO RESPRAY FRONT BUMPER, BOTH FRONT FENDERS, BONNET, HINGES AND BOTH FRONT DOORS.	\$	5,500.00	\$ 1,650.00
8	TO TOW BACK THE VEHICLE FROM ACCIDENT SCENE.	S/N \$	280.00	
9	TO CARRY OUT PRE/POST DIAGNOSTIC CHECK.	S/N \$	384.00	\$ 384.00
TOTAL LABOUR CHARGES		:	\$ 16,104.00	\$ 8,364.00

55 UBI ROAD 1, SINGAPORE 408699
 TEL : 6366 2323 FAX : 6841 1183
 EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SJN 7516 R

			DAMAGED PARTS & PRICES		
S/N	PARTS DESCRIPTION	QTY	S/NETT	REMARKS	
1	FRONT BUMPER	1	\$ 2,377.00	\$	1,901.60
2	FRONT BUMPER FIXING PARTS	1	\$ 393.00		
3	FRONT BUMPER SECURING STRIP	2	\$ 79.00		
4	FRONT BUMPER GRILLE - CENTER	1	\$ 219.00	\$	174.80
5	FRONT BUMPER CLOSING ELEMENT - LOWER CENTRE	1	\$ 293.00	\$	234.00
6	FRONT BUMPER AIR GUIDE - LH / RH	2	\$ 102.00		
7	FRONT BUMPER CLOSING ELEMENT - UPPER CENTRE	1	\$ 293.00	\$	234.00
8	FRONT BUMPER AIR GUIDE GRILLE - LH / RH	2	\$ 302.00	\$	240.80
9	FRONT BUMPER TRIM - LH / RH	2	\$ 108.00		
10	RADIATOR GRILLE	1	\$ 1,754.00	\$	1,403.20
11	FRONT BUMPER FOAM FILLER PIECE	1	\$ 212.00	\$	169.20
12	FRONT BUMPER REINFORCEMENT BEAM	1	\$ 899.00	\$	719.20
13	FRONT BUMPER GUIDE SECTION - LH / RH	2	\$ 82.00	\$	32.24
14	FRONT BUMPER BRACKET - LH / RH	2	\$ 508.00	\$	406.40
15	FRONT BUMPER TOP COVER	1	\$ 143.00	\$	114.00
16	CAUTION SIGN STICKER	1	\$ 16.00	\$	12.40
17	AIR CONDITIONER STICKER	1	\$ 9.00	\$	6.64
18	FRONT BUMPER BRACKET	1	\$ 154.00	\$	122.80
19	FRONT BUMPER SUPPORT - LH / RH	2	\$ 64.00	\$	51.04
20	FRONT PARKING AID SENSOR - INNER / OUTER	4	\$ 1,062.00		
SUB TOTAL SPARE PARTS			\$ 9,069.00	\$	5,822.32

ALL CHARGES ARE NOT INCLUSIVE OF GST
 LEGEND: REMARKS (OK) = APPROVED, REMARKS (X) = NOT APPROVED
 SPARE PARTS ARE SPECIAL NETT.

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SJN 7516 R

			DAMAGED PARTS & PRICES		
S/N	PARTS DESCRIPTION	QTY	S/NETT	REMARKS	
		<i>c/f</i>		<i>\$</i>	<i>5,822.32</i>
21	FRONT PARKING AID SEAL RING	4	\$ 10.00		
22	FRONT BUMPER WIRING SET	1	\$ 642.00		
23	HORN HIGH TONE - LH	1	\$ 134.00		
24	HORN LOW TONE - RH	1	\$ 139.00		
25	HORN BRACKET - LH / RH	2	\$ 66.00		
26	FRONT FENDER - LH / RH	2	\$ 2,454.00	<i>\$</i>	<i>981.60</i>
27	FRONT FENDER ATTACHMENT PARTS	1	\$ 225.00		
28	FRONT FENDER CLOSING ELEMENT - LH / RH	2	\$ 162.00	<i>\$</i>	<i>64.24</i>
29	FRONT FENDER BRACKET - LH / RH	2	\$ 82.00	<i>\$</i>	<i>32.72</i>
30	FRONT FENDER DEFORMATION ELEMENT BRACKET - LH / RH	2	\$ 110.00		
31	FRONT FENDER RIVET	13	\$ 50.00	<i>\$</i>	<i>39.52</i>
32	FRONT FENDER BRACE - LH / RH	2	\$ 264.00		
33	FRONT WHEEL HOUSING LINER - LH / RH	2	\$ 518.00		
34	FRONT WHEEL HOUSING LINER ATTACHMENT PARTS	1	\$ 149.00		
35	FRONT WHEEL SPOILER - LH / RH	2	\$ 164.00		
36	FRONT SPOILER - LH / RH	2	\$ 79.00		
37	FRONT FENDER LEDGE COVER - LH / RH LONG	2	\$ 70.00	<i>\$</i>	<i>27.52</i>
38	HEADLIGHT COVER - LH / RH	2	\$ 98.00	<i>\$</i>	<i>38.64</i>
39	BONNET	1	\$ 3,425.00	<i>\$</i>	<i>2,740.00</i>
40	BONNET ATTACHMENT PARTS	1	\$ 431.00		
SUB TOTAL SPARE PARTS		:	\$ 9,272.00	<i>\$</i>	<i>9,746.56</i>

ALL CHARGES ARE NOT INCLUSIVE OF GST
 LEGEND: REMARKS (OK) = APPROVED, REMARKS (X) = NOT APPROVED
 SPARE PARTS ARE SPECIAL NETT.

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SJN 7516 R

			DAMAGED PARTS & PRICES	
S/N	PARTS DESCRIPTION	QTY	S/NETT	REMARKS
		<i>c/f</i>		<i>\$ 9,746.56</i>
41	BONNET HINGE - LH / RH	2	\$ 680.00	
42	BONNET IMPACT PROTECTION - CENTER / LH / RH	3	\$ 93.00	<i>73.2</i>
43	BONNET STRIKER - LH / RH	2	\$ 112.00	<i>89.12</i>
44	BONNET LOCK	2	\$ 455.00	<i>364</i>
45	BONNET BOWDEN CABLE	1	\$ 64.00	<i>50.56</i>
46	BONNET RELEASE LEVER	1	\$ 15.00	
47	BONNET BOWDEN CABLE - CENTER	1	\$ 64.00	
48	BONNET BOWDEN CABLE COVER	1	\$ 11.00	
49	BONNET LOCK CABLE - RH	1	\$ 82.00	
50	PLENUM CHAMBER COVER	1	\$ 108.00	
51	ENGINE SOUND ABSORBER	1	\$ 382.00	<i>305.6</i>
52	HEADLIGHT - LH / RH	2	\$ 16,344.00	<i>6537.6</i>
53	HEADLIGHT HOSE	2	\$ 83.00	
54	HEADLIGHT COMPENSATING PIECE	2	\$ 89.00	
55	HEADLIGHT COMPENSATING PIECE	2	\$ 93.00	
56	HEADLIGHT COMPENSATING PIECE	2	\$ 89.00	
57	LIFT CYLINDER - LH / RH	2	\$ 462.00	
58	LIFT CYLINDER BRACKET	2	\$ 14.00	
59	LIFT CYLINDER CORRUGATED PIPE	1	\$ 107.00	
60	LOCK CARRIER	1	\$ 1,478.00	<i>901.6</i>
SUB TOTAL SPARE PARTS			\$ 20,825.00	\$ 18,068.24

ALL CHARGES ARE NOT INCLUSIVE OF GST
 LEGEND: REMARKS (OK) = APPROVED, REMARKS (X) = NOT APPROVED
 SPARE PARTS ARE SPECIAL NETT.

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SJN 7516 R

			DAMAGED PARTS & PRICES	
S/N	PARTS DESCRIPTION	QTY	S/NETT	REMARKS
		<i>c/f</i>		<i>\$ 18,068.24</i>
61	LOCK CARRIER SUPPORT - LH / RH	2	\$ 85.00	
62	CHARGE AIR COOLER	1	\$ 654.00	<i>\$ 522.80</i>
63	CHARGE AIR COOLER PRESSURE HOSE - RH	1	\$ 413.00	
64	CHARGE AIR COOLER PRESSURE PIPE - LH	1	\$ 496.00	
65	A/C CONDENSER	1	\$ 683.00	<i>\$ 546.00</i>
66	A/C CONDENSER REFRIGERANT LINE	1	\$ 186.00	
67	A/C CONDENSER REFRIGERANT LINE	1	\$ 381.00	
68	OUTSIDE TEMPERATURE SENSOR BRACKET	1	\$ 21.00	<i>\$ 16.32</i>
69	RADIATOR	1	\$ 1,013.00	
70	RADIATOR FAN RING	1	\$ 292.00	
71	RADIATOR FAN CONTROL UNIT	1	\$ 2,489.00	
72	READY-MIX COOLANT	6	\$ 297.00	<i>\$ 237.12</i>
73	RADIATOR AIR GUIDE - LH / RH INNER	2	\$ 102.00	<i>\$ 80.16</i>
74	RADIATOR AIR GUIDE - LH / RH OUTER	2	\$ 38.00	<i>\$ 29.28</i>
75	RADIATOR AIR GUIDE - UPPER / LOWER	2	\$ 44.00	
76	INTAKE AIR DUCT - RH	1	\$ 25.00	
77	INTAKE AIR GUIDE	1	\$ 61.00	
78	INTAKE AIR DUCT HOSE	1	\$ 110.00	
79	AIR FILTER	1	\$ 418.00	
80	AIR MASS METER	1	\$ 629.00	
SUB TOTAL SPARE PARTS			\$ 8,437.00	<i>\$ 19,499.92</i>

ALL CHARGES ARE NOT INCLUSIVE OF GST
 LEGEND: REMARKS (OK) = APPROVED, REMARKS (X) = NOT APPROVED
 SPARE PARTS ARE SPECIAL NETT.

55 UBI ROAD 1, SINGAPORE 408699
 TEL : 6366 2323 FAX : 6841 1183
 EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SJN 7516 R

			DAMAGED PARTS & PRICES	
S/N	PARTS DESCRIPTION	QTY	S/NETT	REMARKS
		<i>c/f</i>		<i>\$ 19,499.92</i>
81	FRONT NOISE INSULATION	1	\$ 640.00	
82	FRONT WINDOW SLOT SEAL TRIM STRIP - LH / RH	2	\$ 688.00	
83	FRONT NO PLATE	S/N	\$ 60.00	<i>\$ 60.00</i>
84	SUNDRIES		\$ 500.00	<i>\$ 127.84</i>
TOTAL SPARE PARTS		:	\$ 49,491.00	<i>\$ 19,687.76</i>
TOTAL LABOUR CHARGES		:	\$ 16,104.00	<i>\$ 8,364.00</i>
GRAND TOTAL		:	\$ 65,595.00	<i>\$ 28,051.76</i>

ALL CHARGES ARE NOT INCLUSIVE OF GST
 LEGEND: REMARKS (OK) = APPROVED, REMARKS (X) = NOT APPROVED
 SPARE PARTS ARE SPECIAL NETT.
 bi-28/10/22

55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

NAME :
SURVEYED DATE :
AUTHORISED DATE :
EXCESS COST :
LIABILITY :
REMARKS :

PLEASE NOTE : THIS ESTIMATE IS BASED ON VISUAL INSPECTION OF THE AFFECTED VEHICLE. SHOULD WE REQUIRE FURTHER LABOUR CHARGES AND SPARE PARTS IN THE PROGRESS OF REPAIR, WE SHALL INFORM YOU ACCORDINGLY.
FOR INSPECTION OF VEHICLE, PLEASE REFER TO MS. NORAH KHAI AT TEL: 6768 9828 / 6768 9911 FOR APPOINTMENT.

YOURS FAITHFULLY,
PREMIUM AUTOMOBILES PTE LTD

JOHNNY BOO
BODY REPAIR MANAGER

ALLAN WU
CLAIMS CONSULTANT