

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CC3/TMI22009492/KWCE2**Date:** 11/10/2022**REFERENCE**

Handling Insurer:	Tokio Marine Insurance Singapore Ltd	Policy No:	MN000212		
Claimant Vehicle No :	SHD5713C	Insured Vehicle No :	SLJ3716D		
Date of Loss:	08/09/2022	Nature of Claim:	TP	Claim No:	M2205602

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SHD5713C	Engine No:	2ZR2B55786
Make & Model:	TOYOTA PRIUS, 1.8 5DR HATCHBACK (A)	Chassis No:	JTDKB3FU803074537
Reg. Date:	26/10/2018 (Man. Year: 2018)	Odometer:	325537 km
Colour:	Metallic Pearl White/Red		
Engine Capacity:	1798 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	195/65 R15	Rear Tyre Size:	195/65 R15
Front Left Side:	Sailun 8 mm	Rear Left Side:	Sailun 8 mm
Front Right Side:	Sailun 8 mm	Rear Right Side:	Sailun 8 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	1,918.97	45.00	1,873.97	97.65
Miscellaneous Items	0.00	0.00	0.00	
Labour	3,590.00	370.00	3,220.00	89.69
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Gross Total (S\$)	5,508.97	415.00	5,093.97	92.47
+ GST 7.00/7.00% (S\$)	385.63	29.05	356.58	92.47
Nett Amount (S\$)	5,894.60	444.05	5,450.55	92.47

INSPECTION

Date of Assignment:	10/10/2022		Trans cab Auto Service - Ang Mo Kio (HQ)
Date Inspected:	26/09/2022	Inspected At:	2 Ang Mo Kio Street 63
Estimated Period of Repair:	1.0 days		Singapore 569111

Adjuster: KENNETH KONG**Manager:** XinYu*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

REPAIR DETAILS

Reference		
Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 11 Oct 2022)
Parts:	144	TOYOTA PRIUS 1.8 5DR HATCHBACK (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SHD5713C)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*COVER, FRONT BUMPER	Repair	516.00 FL	*- FL
2	1		*ABSORBER, FRONT BUMPER ENERGY	Serviceable	79.60 FL	*- FL
3	1		*REINFORCEMENT SUB-ASSY, FRONT BUMPER	Repair	716.60 FL	*- FL
4	1		*GRILLE SUB-ASSY, RADIATOR	Serviceable	346.00 FL	*- FL
5	1		*GRILLE, RADIATOR, LOWER NO.1	Serviceable	170.10 FL	*- FL
6	1		*BRACKET, FRONT BUMPER EXTENSION MOUNTING	Repair	103.40 FL	*- FL
7	1		*STAY SUB-ASSY, FRONT BUMPER, LH	Serviceable	47.50 FL	*- FL
8	1		*BRACKET, FRONT BUMPER SIDE, LH	Serviceable	59.30 FL	*- FL
9	1		*STAY SUB-ASSY, FRONT BUMPER, RH	Serviceable	47.50 FL	*- FL
10	1		*BRACKET, FRONT BUMPER SIDE, RH	Serviceable	59.30 FL	*- FL
11	1		*FRT BUMPER CLIP	Not Necessary	65.00 FS	*- FS
12	1		*FRT NO PLATE	Dented	180.00 FS	*45.00 FS
13	1		*FRT LH BUMPER RETAINER CLIP	Not Necessary	65.00 FS	*- FS
						F=Franchise part. S=SpcNett. L=ListItemDisc.
					Sub Total (\$\$)	2,455.30 45.00
					- List Item Discount on L Items 25.00/25.00% (\$\$)	536.33 0.00
					Total Parts (\$\$)	1,918.97 45.00

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO REMOVE AND REFIT INTERIOR FITTINGS, TRIMINGS, GARNISH, FITTINGS AND OTHER, TO ENABLE REPAIR	New	380.00	0.00
2	PANEL BEATING, KNOCKING AND STRAIGHTENING THE NECESSARY PORTION, REMOVE AND RENEWAL OF PARTS, ADJUST AND REALIGN THE SAME	New	1,400.00	150.00
3	PUTTY AND SPRAY PAINTING OF THE AFFECTED PORTION	New	1,400.00	220.00
4	TO RUST-PROOFING AND APPLY UNDERCOAT OF THE AFFECTED AREAS	New	240.00	0.00
5	TO CHECK ELECTRICAL LIGHTING CONCERNED	New	170.00	0.00
Gross Labour Cost (\$)			3,590.00	370.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >