



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

TAX INVOICE

CHINA TAIPING INSURANCE (S) PTE LTD

INV No. AC2304639

3 ANSON ROAD #16-00
SPRINGLEAF TOWER
SINGAPORE 079909

INV Date 19/07/2023
Reference CC3/CTI22009493/Gya3q2
Code CTI

PROFESSIONAL SERVICE FEE

Vehicle No. SHC 2233X
Insured Veh. GBK 3808K
Claim No. SNM22D206886/C02
Policy No. DMCVSNW00072202200
Accident Date 22/09/2022
Inspection Date 23/09/2022

Description	Total
Third Party Express Settlement	400.00
Subtotal	400.00
GST (8%)	32.00
Grand Total	432.00

We shall be glad if you could forward the payment at your early convenience.

Cheque should be crossed and made payable to **'LKK Auto Consultants Pte Ltd'**

LKK Auto Consultants Pte Ltd

LKM



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
CHINA TAIPING INSURANCE (S) PTE LTD 3 ANSON ROAD #16-00 SPRINGLEAF TOWERSINGAPORE 079909			Ref: CC3/CTI22009493/Gya3q2 Date: 19/07/2023 Code: CTI	
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	GBK 3808K	Veh. Inspected	SHC 2233X	
Policy No.	DMCVSNW00072202200	Coverage (\$)	0.00	
Claim No.	SNM22D206886/C02	Excess (\$)	0.00	
Assign From		Assign Date	23/09/2022	
2. Vehicle Particulars & Condition				
Make & Model	TOYOTA PRIUS	c.c	1798	
Engine No.	HIDDEN	Year of Reg.	2017	
Chassis No.	JTDKB3FU403565154	Colour	BLUE	
Odometer	655516 KM	Steering	IN ORDER	
Brakes	IN ORDER	Modification	STANDARD ALLOY RIM	
General	GOOD			
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre	195/65 R15	WEST LAKE	6 mm	
L/H Front Tyre	195/65 R15	WEST LAKE	6 mm	
R/H Rear Tyre	195/65 R15	WEST LAKE	6 mm	
L/H Rear Tyre	195/65 R15	WEST LAKE	6 mm	
4. Description of Damages				
THE VEHICLE SUSTAINED DAMAGES AT THE O/S BODY. DAMAGES SEE DETAILS.				
5. General Information				
Accident Date	22/09/2022	Inspection Date	23/09/2022	
Survey held at	COMFORTDELGRO ENGINEERING PTE LTD 59 LOYANG DRIVE SINGAPORE 508969			
5a. Remarks				
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
5b. Estimate Days of Repair				
ESTIMATED NORMAL PERIOD FOR REPAIR:			4 Working Days	



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 1

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SHC 2233X

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	<u>REPLACEMENT OF PARTS</u>			
1	FRONT DOOR RH	TO REPAIR SEE LABOUR	1,264.00	-
1	REAR DOOR RH	BENT	1,258.30	1,258.30
1	ROCKER PANEL GARNISH RH	DEFORMED	576.00	576.00
1	REAR FENDER SHIELD RH	NOT NECESSARY	134.20	-
	LESS 25% DISCOUNT		-808.13	-458.58
			2,424.37	1,375.72
	<u>SPECIAL NETT ITEMS</u>			
1	REAR DOOR APPS RH (SN)	NECESSARY	80.00	80.00
1	REAR DOOR ADV STICKER (SN)	NECESSARY	100.00	100.00
1	FRONT DOOR COMFORTDELGRO RH (SN)	NECESSARY	75.00	75.00
1	FRONT DOOR ADV.STICKER RH (SN)	NECESSARY	100.00	100.00
1	REAR FENDER ADV.STICKER RH (SN)	NECESSARY	100.00	100.00
1	ROCKER PANEL GARNISH RH (SN)	NECESSARY	100.00	100.00
1	REAR BUMPER ADV.STICKER (SN)	NECESSARY	50.00	50.00
			605.00	605.00
	<u>LABOUR</u>			
	PANEL BEATING-REAR FENDER RH ETC.INCLUSIVE OF THE REPAIR OF FRONT DOOR RH .		800.00	750.00
	SPRAY PAINTING CHARGE -REAR BUMPER ETC.		1,500.00	1,000.00
	TUFF KOTE.	NOT NECESSARY	100.00	-
	TRANFER 2 DOORS.		240.00	60.00
			2,640.00	1,810.00
	GRAND TOTAL		5,669.37	3,790.72
	RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)			3,050.00

Report Ref No. CC3/CTI22009493/Gya3q2

XING GUO QIANG

M.MATAI, AMSAE-A

Automotive Assessor

HO LEONG CHUAN

Automotive Assessor

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

PHOTOGRAPHS FOR VEHICLE NO. SHC 2233X

INSPECTION





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

PHOTOGRAPHS FOR VEHICLE NO. SHC 2233X

RE-INSPECTION

