



Main Office : No. 22, Jalan Kilang, Singapore 159419
Tel: 6476 3333 Fax: 6271 5891

Service Centre : Block 100B, Bukit Merah Lane 3,
#01-04/06/08/116, Singapore 159722
Tel: (65) 6476 3333 (8 Lines) Fax: (65) 6270 8314
www.mova.com.sg
GST Reg. No: M2-0065864-2

Mova Spray Centre
2K Oven Spray Painting System

Power-M Automotive Pte Ltd
Specialise In Car Air-con Services,
Car Audio & Hi-Fi System.

Hilton Car Rental Centre

Hilton Auto Trading
Dealing In New/Used Cars, Hire Purchase & Insurance.



INSURER: Allianz Insurance Singapore Pte. Ltd. (HQ)

PARTICULARS OF CLAIM

Claim Type:	OD (OWN DAMAGE)	Ref. No:	
Policy No:	SP2002564379-01	Date of Loss:	26/09/2022
Vehicle Reg. No.:	SLF3844M	Driveable?	
Driver Age/Info:		Party At Fault:	UNKNOWN
TP Injury Involved?	NO	Third Party Involved?	YES
Insured/Claimant:	BOON BEN BERNARD TAN		
Make/Model:	MAZDA BIANTE, 2.0 SKYACTIV-G SP.6EAT (A)	Vehicle Reg. Date:	24/08/2016
Vehicle Colour:	WHITE	Chassis No:	JM6CC1071G0110183
Engine No:	PE30927227		
Odometer:	127984 KM		
Paint Type:			
Total Loss?	NO		
Est. Duration of Repair (day)	7		
Present Location:	MOVA AUTOMOTIVE PTE LTD (BUKIT MERAH)		

COST OF CLAIMS

	Amount
Parts	6,004.30
Miscellaneous Items	0.00
Labour	1,460.00
Paintwork Labour	0.00
Towing	0.00
Gross Total (S\$)	7,464.30
+ GST 7.00% (S\$)	522.50
Nett Amount (S\$)	7,986.80

This claim is handled by: ONG

Generated using Merimen e-Claims Internet Estimation & Adjusting System

AIR DETAILS

Reference

Part Source: MRM-SG Version: 1.0 (Last Synchronised: 27 Sep 2022)
 Parts: M1-MPV MAZDA BIANTE 2.0 SKYACTIV-G SP.6EAT (A) (Catalogue:Merimen Singapore 1.0)
 Labour: Repairer's (Price-denominated Standard List)
 Print Code: (Unsubmitted, no print-code for SLF3844M)
 Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page
 Further Info: Items/values not in reference catalogue are prefixed with an asterisk *.

Estimates on Parts

No.	Qty	Part No.	Particulars	%Disc	%Depr	Amount	
1	1		*FRONT GRILLE / RR				
2	1		*FRONT GRILLE TOP MOUNTING LH (CHROME) / BR	0.00	0.00	*1,350.00 F	✓
3	1		*FRONT GRILLE LOWER MOUNTING LH (CHROME) / BR GR	0.00	0.00	*290.00 F	✓
4	1		*FRONT GRILLE CLIPS / RR	0.00	0.00	*320.00 F	✓
5	1		*FRONT BUMPER / RR	0	0.00	*30.00 FS	20 Nett
6	1		*FRONT BUMPER SIDE RETAINER BRACKET LH / BR	0.00	0.00	*680.00 F	✓
7	1		*FRONT BUMPER UPPER BOLDER BRACKET LH / BR	0.00	0.00	*48.00 F	✓
8	1		*FRONT BUMPER FOG LAMP FINISHER COVER LH / RR	0.00	0.00	*65.00 F	✓
9	1		*FRONT BUMPER CLIPS / RR	0.00	0.00	*110.00 F	✓
10	1		*FRONT NUMBER PLATE / RR	0	0.00	*40.00 FS	30 nett
11	1		*FRONT NUMBER PLATE HOLDER / NN	0	0.00	*30.00 FS	
12	1		*FRONT SUPPORT PANEL / NN	0	0.00	*20.00 FS	
13	1		*FRONT HEADLAMP LH / BR	0.00	0.00	*360.00 F	✓
14	1		*FRONT FENDER LH / BR	0.00	0.00	*1,350.00 F	✓
15	1		*FRONT FENDER INNER LINER LH / RR	0.00	0.00	*260.00 F	✓
16	1		*FRONT FENDER LINER CLIPS LH / RR	0.00	0.00	*110.00 F	✓
17	1		*FRONT FENDER UPPER LAMP LH / RR	0	0.00	*40.00 FS	20 nett
18	1		*FRONT BONNET (REPAIR) / RR	0.00	0.00	*370.00 F	✓
19	1		*FRONT WHEEL HOUSE LH (REPAIR) / RR	0.00	0.00	-	

F=Franchise part, S=SpcNett.

Sub Total (S\$) 5,473.00

+ Margin on L,N Items 10.00% (S\$) 531.30

Total Parts (S\$) 6,004.30

Report was unsubmitted during this print-out.
 Generated using Merimen e-Claims IEAS

nett - 70 5313
 +10%
 5844.30

Estimates on Miscellaneous Items
are no new miscellaneous items selected.

Estimates on Labour

No	Particulars	Lab.Type	Amount
Labour Items			
1	TO CHECK WIRING & ELECTRICAL SYSTEM	New	50 60.00
2	TO REMOVE, REPLACE, REPAIR & READJUST FRONT ACCIDENT AREAS SUCH AS FRONT BONNET, FRONT BUMPER, FRONT SUPPORT PANEL, FRONT WHEEL HOUSE LH & FRONT FENDER LH. BACK TO ORIGINAL CONDITIONS	New	600.00 /
3	TO SUPPLY PAINT & FURNISHING MATERIALS AT FRONT BONNET, FRONT BUMPER, FRONT WHEEL HOUSE LH & FRONT FENDER LH	New	800.00 /
Gross Labour Cost (\$\$)			1,460.00 1450

Report was unsubmitted during this print-out.
Generated using Merimen e-Claims IEAS

< END OF ESTIMATES >

Stew (LKK)
27/9/22, 5.30pm

OD-MAL
Excise - 2
P/P

total - 7364.30

- LKK Auto Consultants hence notify the Repairer of the following:
- To resurvey before/after spray painting
 - To display damaged part(s) during resurvey
 - Parts prices are subject to confirmation
 - Third party survey is on a "Without Prejudice" basis
 - No illegal modification(s) is allowed
 - Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date:

MAL
6
LP