

PC 9960P: 2010 August. TPAx1.

Veron.

Scania K1B4X2 11705cc

152K4x20001863470

Rees Bumper. ~~HP~~ 3200 (SN) X

Rees Bumper Frame. ~~MM~~ 1500 (SN) X

Rees Corner Bumper LH. ~~could~~ 1280 (SN) 750 (SN)

Rees Corner Bumper Lamp LH. ~~could~~ 280 (SN) 180 (SN)

Rees Corner Bumper Sticker LH. ~~HP~~ 100 (SN) 50 (SN)

Tail Lamp LH. ~~HP~~ 780 (SN) X
980 (SN)

Panel Beating

Spray Painting

Wiring.

2 spray left coil.

~~800 (SN)~~ 250

560 ~~600 (SN)~~ 250

~~100 (SN)~~ 30

~~100 (SN)~~ 30

total: 1340

W/S: 1.2K 02 Days

8740

LKK Auto Consultants hence notify

the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature: