

LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile					
	AXA INSURANCE	PTE LTD	Ref:	CS/ASM22009504/Gvy3e2	
	8 SHENTON WAY #24-01 AXA TOWER SINGAPORE 068811		Date:	07/11/2022	
	ATTN: LOH CYNTI	AIA	Code:	ASM	
1.	Policy Particulars :- THIRD PARTY CLAIM				
	Insured Veh.	SHD 7130X	Veh. Inspected	SMZ 9699J	
	Policy No.	VFX/P2419138	Coverage (\$)	0.00	
	Claim No.	S2M04BOV	Excess (\$)	0.00	
	Assign From	LOH CYNTHIA	Assign Date	27/09/2022	
2. Vehicle Particulars & Condition					
	Make & Model	TOYOTA LEXUS RX350	c.c	3456	
	Engine No.	HIDDEN	Year of Reg.	2016	
	Chassis No.	JTJBZMCA802011436	Colour	WHITE	
	Odometer	100187 KM	Steering	IN ORDER	
	Brakes	IN ORDER	Modification	SPORTS RIM	
	General	GOOD			
3.	3. Conditions of Tyres				
		Size	Make	Balance	
	R/H Front Tyre	235/55 R20	BRIDGESTONE	6 mm	
	L/H Front Tyre	235/55 R20	BRIDGESTONE	6 mm	
	R/H Rear Tyre	235/55 R20	BRIDGESTONE	6 mm	
	L/H Rear Tyre	235/55 R20	BRIDGESTONE	6 mm	
4.	Description of Damages				
	THE VEHICLE SUSTAINED DAMAGES AT THE FRONT N/S PORTION.				
	DAMAGES SEE DETAILS.				
5.	General Information				
	Accident Date	26/09/2022	Inspection Date	27/09/2022	
	Survey held at	AB ENGINEERING PTE LTD			
	25 SENANG CRESCENT, SINGAPORE 416598				
5a.					
	A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
5b.	Estimate Days of Repair				
	ESTIMATED NORMAL PERIOD FOR REPAIR: 4 Working Days				