

AB ENGINEERING PTE LTD

Co. Reg No: 202117273R

10 KAKI BUKIT ROAD 2 #01-25, FIRST EAST CENTRE, SINGAPORE 417868

Tel : 8858 6282

ADJUSTMENT ON REPAIR COST & REPLACEMENT OF PARTS

Vehicle No: SMZ9699J

Report No : SA1X229Q0001

Chassis No: JTJBZMCA802011436

Engine No: SNB2574X

Date : 27/9/2022

MAKE: TOYOTA

MODEL: LEXUS RX350 LUXURY AT SR

TYPE : COMMERCIAL

Replacement of Damaged Parts

S/No.	Description	Qty	Our Recommendation
Parts Items			
1	Headlamp assy - LH / BR	1	7733.90 ✓
2	Front bumper / Re	1	1196.90 ✓
3	Front bumper retainer - LH / cut	1	133.20 ✓
4	Front bumper clip / m/c	10	80.00 ✓
5	Front bumper cover - LH / cut	1	85.40 ✓
6	Front bumper lower skirt - LH / cut	1	142.60 ✓
7	Front bumper lip - Center ✓ CRA	1	170.70 ✓
8	Front fog lamp - LH ✓ CRA	1	303.80 ✓
9	Fog lamp garnish - LH /	1	79.90 ✓
10	Front fog lamp moulding chrome - LH / cut	1	89.90 ✓
11	Front fender - LH X Repair	1	1498.90
12	Front fender arch - LH / cut	1	239.60 ✓
13	Front fender arch clip - LH / m/c	10	60.00 ✓
14	Front bonnet X Repair	1	3131.90
			\$14,946.70 10315.9
Less 10%			\$1,494.67
Total Parts:			\$13,452.03 9284.31

Labour Charges

- * To diagnose and calibrate front sensor wiring system, safety systems, parking aid sensors & re-set of same. \$600.00 80
- * To diagnose re-calibrate adaptive front lighting system (Lexus triple-beam led headlamps), with a suite sensors & re-set of same. \$550.00 X
- * To re-set wheel alignment & re-set of same. \$200.00 X

* To dismantle damaged parts; to heat/weld, cut-off the front bonnet, front bumper, front fender LH, front chassis frame LH, including replacement of parts and align where necessary, to refit and adjust of same.	\$850.00	400
* To putty and spray paint (premium) on affected areas.	\$1,800.00	750
* To apply rust-proofing on replaced and repaired panels.	\$150.00	60
Total Labour:	\$4,150.00	

Final Repair Cost to Vehicle No : SMZ9699J

Amount	\$17,602.03	20,286.37
Lump Sum Discount -20%	\$ 3,520.41	
Total	\$14,081.62	
Add GST 7%	\$ 985.71	
Grand Total	\$15,067.34	

11661.42

4 Days.

part by part.

before paint photos.

Guo Qiang - 82880282

27/9/22.

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before painting
- To display damaged parts during resurvey
- Parts price to be agreed on "no bid" basis
- Third party to be agreed on "no bid" basis
- No other work to be done
- Supply of materials to be agreed on and is subject to the company

Acknowledged by Repairer

Signature

Date