

ASS. REC. BY:

REF:

CS/AGI 22009507/Day³

ASSIGNMENT

COE May 2027

From: _____ Date: _____

Estimated Cost: _____

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: _____

at Workshop m/s _____

of _____

Insured: _____

Policy No. _____

Claims No. _____

Sum Insured: _____ Excess: _____

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.

N/S	O/S

Bal. or Market Value: _____

IDAC Accident Rpt: _____ Consistent?: Yes or No

GIA / PR Seen: _____ Consistent?: Yes or No

Est. Repairs: 8 days Res.: Yes or NoLum Sum: 10 % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: _____ Person Contacted: _____

Vehicle: IN / OUT

Veh No: SH 81723 Yr Regn: May / 2019

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: Hyundai Ionix c.c. 1580Colour: Blue A/C: Insured / Std / NI / NASp. Reading: 346250 T/Radio: Insured / Std / NI / NAEng/No: G4LEKU210087C/No: KMHCB51CVKW146081

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt or

Brake: Inorder / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size: F: 195/65R15R: 11

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or Westlake

Front Rear

R/Bal. 5 mm R/Bal. 5 mmL/Bal. 5 mm L/Bal. 5 mmD.O.A. 24/09/2022 D.O.I. 27/09/2022Survey held at Big West sm Ming

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

O/S Front

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

Budget Direct 8536048614/2/23 from 2/5 9,300/- into 8 days of rep
(Red. \$ 18,329,31, 66%)

Date/Time, File Pass to?

1) 16/2/23

Date/Time, File Return to?

2)

☐ : Preli. Report☐ : Final ReportDays Of Repair: 8Resurvey No. of Trip: 2

Survey Fee:

Transportation:

S + RS \$

Photos

Others

TOTAL

Add Fee: ☐ : Site Insp (\$)☐ : Interview (\$)☐ : Tech. Invs (\$)☐ : Weekend (\$)Report Format: TPLump Sum / I.B.I: (\$ 9300)

Customer: LIM TAN
 Company: 01-42
 License NO: SHA 8172S
 Odometer:

Date: 9/27/2022 9:47 AM
 VIN
 Technician:
 Order NO:

VEHICLE ALIGNMENT REPORT
 HYUNDAI, IONIC AE Series EV, 17-17 (Customized)

Primary Angles

			Initial	Specifications		Final
				Min.	Max.	
Front	Caster	Left	5°10'	4°00'	5°00'	5°30'
		Right	5°02'	4°00'	5°00'	5°24'
	Camber	Left	-0°12'	-1°00'	0°00'	-0°12'
		Right	-2°00'	-1°00'	0°00'	-1°54'
	Toe	Left	-0°09'	-0°03'	0°09'	1°15'
		Right	0°06'	-0°03'	0°09'	-1°15'
		Total	-0°03'	-0°06'	0°18'	0°00'
Rear	Camber	Left	-1°12'	-1°42'	-0°42'	-1°06'
		Right	-1°00'	-1°42'	-0°42'	-1°00'
	Toe	Left	0°27'	0°00'	0°18'	0°27'
		Right	-0°15'	0°00'	0°18'	-0°15'
		Total	0°12'	0°00'	0°36'	0°12'
	Thrust Angle		0°21'	---		0°21'

Secondary Angles

			Initial	Specifications		Final
				Min.	Max.	
SAI	Left		13°26'	13°30'	14°30'	13°26'
	Right		14°32'	13°30'	14°30'	14°32'
Included Angle	Left		13°14'	---	---	13°14'
	Right		12°32'	---	---	12°38'
Toe Out On Turns	Left		---	---	---	---
	Right		---	---	---	---
Max Turn Inside	Left		---	---	---	---
	Right		---	---	---	---
Toe Curve Change	Left		---	---	---	---
	Right		---	---	---	---
Setback	Front		6mm	---	---	6mm
	Rear		2mm	---	---	2mm
Track Width Diff.			-3mm			-3mm
Wheel Base Diff.			4mm			4mm
Front Ride Height	Left		---	---	---	---
	Right		---	---	---	---
Rear Ride Height	Left		---	---	---	---
	Right		---	---	---	---
Frame Angle						---

> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Company
Owner ID:	821R
Vehicle Details	
Vehicle No.:	SH8172S
Vehicle to be Exported:	Yes
Intended Deregistration Date:	30 Sep 2022
Vehicle Make:	HYUNDAI
Vehicle Model:	AE IONIQ HEV 1.6 DCT
Primary Colour:	Blue
Manufacturing Year:	2019
Engine No.:	G4LEKU210087
Chassis No.:	KMHC851CVKU146081
Maximum Power Output:	103.6 kW (138 bhp)
Open Market Value:	\$24,799.00
Original Registration Date:	14 May 2019
First Registration Date:	14 May 2019
Transfer Count:	0
Actual ARF Paid:	\$11,719.00
Intended PARF Rebate Details	
PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	13 May 2027
PARF Rebate Amount:	\$8,789.00
Intended COE Rebate Details	
COE Expiry Date:	13 May 2027
COE Category:	A - Car up to 1600cc & 97kW (130bhp)
COE Period(Years):	8
PQP Paid:	\$22,309.00
COE Rebate Amount:	\$12,878.00
Total Rebate Amount:	\$21,667.00
Message	
Please note that the 8-year COE for this vehicle cannot be further renewed. The vehicle must be de-registered upon COE expiry or when the vehicle reaches its statutory lifespan (if applicable), whichever is earlier.	

The information contained herein is correct as at 26 Sep 2022

OK

BIFROST AUTO PTE LTD

REPAIR ESTIMATE

DATE: 26-Sep-22

INSURANCE: Budget Direct

MODEL: HYUNDAI IONIC

VEHICLE NO.: SH 8172 S

Description	Qty	List Price	Amount
Bonnet <i>HW</i>	1	\$ 2,253.80	\$ 2,253.80
Bonnet Hinge (LH/RH) <i>HW</i>	2	\$ 118.70	\$ 237.40
Bonnet Moulding <i>HW</i>	1	\$ 41.40	\$ 41.40
Bonnet Lock <i>HW</i>	1	\$ 127.30	\$ 127.30
Bonnet Insulator <i>HW</i>	1	\$ 230.10	\$ 230.10
Bonnet Insulator Clips <i>HW</i>	1	\$ 15.00	\$ 15.00
Front Bumper Cover <i>broken</i>	1	\$ 481.10	\$ 481.10
Front bumper top cover <i>HW</i>	1	\$ 476.30	\$ 476.30
Front Bumper Reinforcement ABSORBER (RH) <i>HW</i>	1	\$ 186.50	\$ 186.50
Front Bumper Moulding Centre Upper <i>HW</i>	1	\$ 368.50	\$ 368.50
Front Bumper Bracket Top (RH) <i>HW</i>	1	\$ 35.00	\$ 35.00
Front Bumper Bracket (RH) <i>SW</i>	1	\$ 28.00	\$ 28.00
Front Bumper Retainer Mounting (RH) <i>HW</i>	1	\$ 65.30	\$ 65.30
Front Bumper Clips 10 pcs <i>HW</i>	1	\$ 25.00	\$ 25.00
Front Bumper Grille (RH) <i>HW</i>	1	\$ 186.90	\$ 186.90
Front bumper air duct (RH) <i>HW</i>	1	\$ 153.80	\$ 153.80
Day Light , RH <i>HW</i>	1	\$ 642.50	\$ 642.50
Headlamp Support Panel Assy <i>CRACK</i>	1	\$ 1,139.30	\$ 1,139.30
Headlamp(RH) <i>scratched / windy broken</i>	1	\$ 3,987.30	\$ 3,987.30
Frt Pillar Upper Cover - outer (RH) <i>distorted</i>	1	\$ 89.60	\$ 89.60
Front Fender(RH) <i>Damage</i>	1	\$ 490.70	\$ 490.70
Front Fender Apron Panel side support (RH) <i>HW</i>	1	\$ 238.80	\$ 238.80
Front Fender Apron Panel (RH) <i>HW</i>	1	\$ 756.20	\$ 756.20
Front Fender Apron Panel Upper(RH) <i>HW</i>	1	\$ 329.00	\$ 329.00
Front Fender Shield (RH) <i>damaged / torn</i>	1	\$ 164.70	\$ 164.70
Frt Door(RH) <i>Damage</i>	1	\$ 1,797.20	\$ 1,797.20
Frt Door Rubber <i>SW</i>	1	\$ 250.00	\$ 250.00
Front Door Regulator (RH) <i>HW</i>	1	\$ 750.40	\$ 750.40
Front Door Power Motor, RH <i>HW</i>	1	\$ 689.20	\$ 689.20
Front Door Hinge Upper (RH) <i>SW</i>	1	\$ 165.76	\$ 165.76
Front Door Hinge Lower (RH) <i>SW</i>	1	\$ 153.70	\$ 153.70
Front Door Check (RH) <i>HW</i>	1	\$ 72.98	\$ 72.98
Front Door Inner Lock (RH) <i>HW</i>	1	\$ 385.60	\$ 385.60
Front Door Protector(RH) <i>HW</i>	1	\$ 186.20	\$ 186.20
Front Door Outer Moulding (RH) <i>HW</i>	1	\$ 110.10	\$ 110.10
Wiper Container ASSY <i>HW</i>	1	\$ 385.40	\$ 385.40
Front Wheel Rim (RH) <i>distorted</i>	1	\$ 1,124.20	\$ 1,124.20
Front Wheel Hub assy (RH) <i>See Down</i>	1	\$ 678.50	\$ 678.50
Front Wheel Hub Cap <i>CRACK</i>	1	\$ 346.40	\$ 346.40
Front Shock Absorber(Assy)(RH) <i>distorted</i>	1	\$ 372.50	\$ 372.50
Front Shock Absorber Mounting (RH) <i>HW</i>	1	\$ 372.50	\$ 372.50
Front Drive Shaft (RH) <i>HW</i>	1	\$ 1,136.70	\$ 1,136.70
Front drive shaft extension RH <i>HW</i>	1	\$ 1,125.80	\$ 1,125.80

2110.30

Rack & Pinion Assy	1	\$ 2,387.40	\$ 2,387.40
STG Tie Rod	1	\$ 125.60	\$ 125.60
STG Tie End	1	\$ 94.70	\$ 94.70
Stabilizer Bar	1	\$ 326.80	\$ 326.80
Stabilizer Bar Link	1	\$ 92.10	\$ 92.10
Front Suspension Lower Arm (RH)	1	\$ 596.80	\$ 596.80
Knuckle Arm (RH)	1	\$ 663.60	\$ 663.60
SUB TOTAL			\$ 27,139.64
LESS 20%			\$ 5,427.93
DISCOUNTED TOTAL			\$ 21,711.71
Front Fender Advertisement Logo (RH)	SN 1	\$ 100.00	\$ 100.00
Emblem-Blue Drive (RH)	SN 1	\$ 26.60	\$ 26.60
Front Door Comfort Logo (RH)	SN 1	\$ 75.00	\$ 75.00
Front Door Advertisement Logo (RH)	SN 1	\$ 100.00	\$ 100.00
Front Tyre(RH)	SN 1	\$ 216.00	\$ 216.00
SUB TOTAL			\$ 517.60
Labour Charge			
Panel Beating	1	\$1,800.00	\$1,800.00
Spray Painting Charge	1	\$1,600.00	\$1,600.00
Wiring Charge	1	\$100.00	\$100.00
Tuff Kote	1	\$100.00	\$100.00
Towing Charge	1	\$80.00	\$80.00
Transfer of Door Mechanism FRONT	1	\$80.00	\$80.00
Re-set Frt Power Window System	1	\$200.00	\$200.00
Four Wheel Alignment	1	\$120.00	\$120.00
Remove/Refix Undercarriage (Frt)	1	\$400.00	\$400.00
Remove/Refix Radiator	1	\$90.00	\$90.00
Remove/Refix Aircon & Refill Gas	1	\$130.00	\$130.00
Remove/Refix Steering Rack/Wheel/Dr Shaft	1	\$150.00	\$150.00
Diagnostic & Resetting To Erase Fault Code	1	\$550.00	\$550.00
TOTAL LABOUR			\$5,400.00
ESTIMATE TOTAL			\$27,629.31

This is an initial estimate based on a visual inspection of the above vehicle. The final repair quantum will be prepared after the vehicle is surveyed by a motor Surveyor appointed by the insurance company. Please send your book value request to: claims_ltr@bifrostauto.com

27/09/2022 @ 1400h

W.A. A.M.

2 lines 8 days

3

2 kl Auto

10,399.16
4/5 9,300/-

- LKK Auto Consultants** hence notify the Repairer of the following:
- To resurvey before/after spray painting
 - To display damaged part(s) during resurvey
 - Parts prices are subject to confirmation
 - Third party survey is on a "Without Prejudice" basis
 - No illegal modification(s) is allowed
 - Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: