



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
HSBC LIFE (SINGAPORE) PTE LTD 10 MARINA BOULEVARD #48-01 MARINA BAY FINANCIAL CENTRE TOWER 2SINGAPORE 018983 ATTN: LOW GARNET			Ref: CS/ASM22009508/Kny3e2 Date: 22/03/2023 Code: HSB	
1. Policy Particulars :- THIRD PARTY CLAIM				
	Insured Veh.	SHA 8155J	Veh. Inspected	SDZ 7711B
	Policy No.	VFX/P2419140	Coverage (\$)	0.00
	Claim No.	S2M04BP1	Excess (\$)	0.00
	Assign From	LOW GARNET	Assign Date	27/09/2022
2. Vehicle Particulars & Condition				
	Make & Model	PORSCHE 924 (M)	c.c	1984
	Engine No.	HIDDEN	Year of Reg.	1980
	Chassis No.	93A0141762	Colour	METALLIC DARK BLUE
	Odometer	17737 KM	Steering	IN ORDER
	Brakes	IN ORDER	Modification	STANDARD ALLOY RIM
	General	GOOD		
3. Conditions of Tyres				
		Size	Make	Balance
	R/H Front Tyre	205/55 R16	DUNLOP	9 mm
	L/H Front Tyre	205/55 R16	DUNLOP	9 mm
	R/H Rear Tyre	205/55 R16	YOKOHAMA	8 mm
	L/H Rear Tyre	205/55 R16	YOKOHAMA	8 mm
4. Description of Damages				
	THE VEHICLE SUSTAINED DAMAGES AT THE FRONT PORTION. DAMAGES SEE DETAILS.			
5. General Information				
	Accident Date	25/09/2022	Inspection Date	28/09/2022
	Survey held at	H C AUTO PTE LTD 160 SIN MING DRIVE #05-09 SIN MING AUTOCITY SINGAPORE 575722		
5a. Remarks				
	A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.			
5b. Estimate Days of Repair				
	ESTIMATED NORMAL PERIOD FOR REPAIR:		4 Working Days	