

H C AUTO PTE LTD

160 Sin Ming Drive # 05-09 Sin Ming Auto City Singapore 575722

Tel : 6457 0678 Fax : 6457 8287

Co. and GST Reg. No. : 200820153N

*Not Authorized
11 Rm 84800k
Henry After Paving
4 days*

Date: 26 / 09 / 2022

ESTIMATE COSTS OF REPAIR

Mr. Toon Chin Shen Esmond

C/o 160 Sin Ming Drive
05-09 Sin Ming Auto City
Singapore 575722

Dear Sir / Madam ,

Vehicle no. : SDZ 7711 B - Porsche 924
Accident date : 25 / 09 / 2022

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Quantity	Descriptions	Amount (\$)
1	1 pc front bumper <i>4200</i>	<i>CM</i> \$ 5,800.00 ✓
2	2 pcs front bumper bracket 1 @ 850.00 <i>280</i>	\$ Oil 1,700.00 ✓
3	2 pcs front bumper stopper 1 @ 328.00	<i>nd slm</i> 656.00 ✓
4	2 pcs headlamp 1 @ 1,800.00	\$ <i>h</i> 3,600.00 X
5	2 pcs headlamp garnish 1 @ 389.00	\$ <i>h</i> 778.00 X
6	1 pc front bumper lower panel	\$ <i>h</i> 2,800.00 X
7	2 pcs front bumper fog lamp 1 @ 480.00	\$ <i>h</i> 960.00 X
8	2 pcs front signal lamp 1 @ 298.00	\$ <i>h</i> 596.00 X
9	1 pc front nose panel	\$ <i>h</i> 2,688.00 X
		\$ 19,578.00
	Less 10%	\$ 1,957.80
		\$ 17,620.20
10	1 pc front no plate	\$ <i>nd</i> 150.00 <i>sn</i> <i>451m</i>
		\$ 17,770.20
	Labour charges	\$ 1,800.00 <i>500l</i>
	To putty and spray painting	\$ 1,800.00 <i>800l</i>
	To reseal and anti-rust	\$ <i>nn</i> 450.00 X
	To check , replace, repair wiring and reset fault code	\$ 800.00 <i>30l</i>
		\$ 22,620.20
	Plus 7% GST	\$ 1,583.41
	Sub_Total	\$ 24,203.61

*break seal & re seal
no. plate*

880l