

JL Perfect Autowork Pte Ltd

Company Reg No: 202136905K

8 Kaki Bukit Ave 4, #08-09 Premier@Kaki Bukit
Singapore 415875

Tel : 6341 6789 Fax: 6341 6778
E-mail:jlperfectautowork@gmail.com



DATE : 26.09.2022

TO : AXA MOTOR CLAIMS DEPTS
VEHICLE NO : GBE2646Z
MODEL : TOYOTA DYNA
DATE OF ACCIDENT : 21.08.2022
TIME OF ACCIDENT : 21:40 HRS

Xiao Tony

WE APPEND HEREUNDER THE ESTIMATED COST OF REPAIRS TO BE CARRIED OUT TO THE ABOVE VEHICLE.

CLAIM DETAIL : PARTS

S/N	DESCRIPTION	QTY	UNIT LIST PRICE	TOTAL LIST PRICE
1	SIDE GATE RH <i>Revised</i>	1	\$ 1,846.00	\$ 1,846.00
2	SIDE GATE SAFETY LOCK RH <i>new</i>	1	\$ 132.10	\$ 132.10
3	SIDE GATE HINGE RH <i>1 piece Revised</i>	6	\$ 95.90	\$ 575.40
4	REAR WHEEL BACK MUDGUARD RH <i>Revised</i>	1	\$ 185.00	\$ 185.00
5	REAR WHEEL BACK MUDFLAG RH <i>new</i>	1	\$ 115.00	\$ 115.00
6	CARGO BED SIDE END PANEL RH <i>Pgs</i>	1	\$ 1,428.00	\$ 1,428.00
7	REAR EXHAUST PIPE BRACKET <i>new</i>	1	\$ 78.90	\$ 78.90

2126.90
1595.17

TOTAL PRICE \$ 4,360.40
LESS 25% \$ 1,090.10
SUB TOTAL PRICE \$ 3,270.30

S/N	DESCRIPTION	QTY	UNIT S/NETT	TOTAL S/NETT
1	SIDE GATE SEALANT RH <i>new</i>	1	\$ 150.00	\$ 150.00
2	SIDE GATE INNER COVER (ALUMINIUM) RH <i>new</i>	1	\$ 680.00	\$ 680.00
3	SIDE GATE COMPANY STICKER <i>new</i>	1	\$ 450.00	\$ 450.00
4	REAR END PANEL SEALANT <i>new</i>	1	\$ 250.00	\$ 250.00
5	REAR TOOLS BOX RH <i>Revised</i>	1	\$ 500.00	\$ 500.00

710

TOTAL \$ 2,030.00

CLAIM DETAILS: LABOUR AND SPRAY PAINTING (REAR)

S/N	JOB DESCRIPTION	PRICE	ADJUSTED COST
1	TO PANEL BEAT, WELD, CUT, ADJUST, KNOCK	\$ 1,400.00	400
2	TO PUTTY, SPRAY PAINT, POLISH WAX	\$ 1,000.00	500
3	REMOVE AND REFIX REAR RAILING	\$ 350.00	80

TO : AXA MOTOR CLAIMS DEPTS
VEHICLE NO : GBE2646Z
MODEL : TOYOTA DYNA
DATE OF ACCIDENT : 21.08.2022
TIME OF ACCIDENT : 21:40 HRS

4	REMOVE AND REFIX CARGO BED COVER ALUMINIUM	\$ 650.00	x
5	REMOVE AND REFIX CANOPY	\$ 350.00	150
6	REMOVE AND REFIX SIDE GATE ALUMINIUM	\$ 200.00	30
7	TO CHECK DIAGNOSTICS OF VEHICLE MANAGEMENT/CONTROL UNITS, RESET MEMORIES TO SPECIFICATION ETC.	\$ 180.00	x

TOTAL \$ 4,130.00

ESTIMATE REPORT

TOTAL PARTS COST : \$ 5,300.30
TOTAL LABOUR COST : \$ 4,130.00
TOTAL REPAIR COST : \$ 9,430.30

NB: THIS IS ONLY AN ESTIMATE AND SHOULD ADDITIONAL WORK BE FOUND NECESSARY TO BE CARRIED OUT IN THE COURSE OF REPAIRS, EXTRA MATERIALS AND LABOUR COST WILL BE CHARGED ACCORDINGLY WHICH HOWEVER, YOU WILL BE INFORMED PRIOR TO ACTION TAKEN.
PARTS PRICES ARE SUBJECT TO CHANGES.

YOURS FAITHFULLY,

IRENE

SERVICE ADVISOR
IRENE
HP : 8297 9787

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

total: 3465.17

4/s: 2750

2750