



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

TAX INVOICE

LONPAC INSURANCE BHD
300 BEACH ROAD
#17-04/07 THE CONCOURSE
SINGAPORE 199555

INV No. AC2300192
INV Date 11/01/2023
Reference CC4/LPC22009513/Kpa3q2
Code LPC2

PROFESSIONAL SERVICE FEE

Vehicle No. GBJ 3007K
Insured Veh. YN 1141A
Claim No. 22/22/22/VC05/026327
Policy No. Z22VC05012037
Accident Date 23/09/2022
Inspection Date 29/09/2022

Description	Total
Third Party Express Settlement	400.00
Subtotal	400.00
GST (8%)	32.00
Grand Total	432.00

We shall be glad if you could forward the payment at your early convenience.

Cheque should be crossed and made payable to **'LKK Auto Consultants Pte Ltd'**

LKK Auto Consultants Pte Ltd

LKM



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

LONPAC INSURANCE BHD

300 BEACH ROAD

#17-04/07 THE CONCOURSESINGAPORE 199555

Ref: CC4/LPC22009513/Kpa3q2

Date: 11/01/2023

Code: LPC2

1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	YN 1141A	Veh. Inspected	GBJ 3007K
Policy No.	Z22VC05012037	Coverage (\$)	0.00
Claim No.	22/22/22/VC05/026327	Excess (\$)	0.00
Assign From	GERALD	Assign Date	27/09/2022

2. Vehicle Particulars & Condition

Make & Model	HYUNDAI STAREX (M)	c.c	2497
Engine No.	HIDDEN	Year of Reg.	2019
Chassis No.	KMFWBX7KLKU068840	Colour	METALLIC GREY
Odometer	10911 KM	Steering	IN ORDER
Brakes	IN ORDER	Modification	NIL
General	GOOD		

3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre	215/70 R16	DELIUM	5 mm
L/H Front Tyre	215/70 R16	DELIUM	5 mm
R/H Rear Tyre	215/70 R16	DELIUM	5 mm
L/H Rear Tyre	215/70 R16	DELIUM	5 mm

4. Description of Damages

THE VEHICLE SUSTAINED DAMAGES AT THE N/S REAR BODY.
DAMAGES SEE DETAILS.

5. General Information

Accident Date	23/09/2022	Inspection Date	29/09/2022
Survey held at	THINK ONE AUTOCARE PTE LTD NO.18 DEFU AVENUE 2 SINGAPORE 539522		

5a. Remarks

A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS.
B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.

5b. Estimate Days of Repair

ESTIMATED NORMAL PERIOD FOR REPAIR:	4 Working Days
-------------------------------------	-----------------------



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 1

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. GBJ 3007K

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
REPLACEMENT OF PARTS				
1	REAR FENDER LH	TO REPAIR SEE LABOUR	2,866.00	-
1	SLIDE DOOR LH	TO REPAIR SEE LABOUR	1,950.00	-
	LESS 10% DISCOUNT		-481.60	-
			4,334.40	-
SPECIAL NETT ITEMS				
1	REAR FENDER STICKER (SN)	NECESSARY	600.00	300.00
1	COMPANY STICKER (SN)	NOT NECESSARY	400.00	-
			1,000.00	300.00
LABOUR				
	TO REMOVE REAR DAMAGED BODY PARTS WITH ALL NECESSARY COMPONENTS /ATTACHMENTS APPLY HOT-WORKS WHERE NECESSARY REPAIR ,RESHAPE BODY DENTED PANELS IN ACCORDANCE WITH FACTORY SPECIFICATIONS REPLACE N AND ALIGN INTO POSITION REFIT ALL NECESSARY COMPONENTS /ATTACHMENTS .INCLUSIVE OF THE REPAIR OF REAR FENDER LH AND SLIDE DOOR LH .		1,200.00	500.00
	TO SPRAY PAINT REPLACED /REPAIRED BODY PARTS INCLUSIVE OF PREPARATORY WORKS AND PAINTING MATERIALS.		1,000.00	400.00
	TO TRANSFER SLIDE DOOR COMPONENTS WITH ALL NECESSARY ATTACHMENT.	NOT NECESSARY	150.00	-
			2,350.00	900.00
GRAND TOTAL			7,684.40	1,200.00
RECOMMENDED COST OF REPAIRS				1,200.00

Report Ref No. CC4/LPC22009513/Kpa3q2

KONG SENG CHEONG

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contact or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

PHOTOGRAPHS FOR VEHICLE NO. GBJ 3007K

INSPECTION





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

PHOTOGRAPHS FOR VEHICLE NO. GBJ 3007K

RE-INSPECTION

