



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

CS3/ASM22004778/Gwy3-1

AXA INSURANCE PTE LTD
8 SHENTON WAY #24-01
AXA TOWERS SINGAPORE 068811

Ref: ~~CS/ASM22004778/Gwy3~~

Date: ~~20/05/2022~~ 27/09/2022

Code: ASM

1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	SKB 9890Y	Veh. Inspected	SX 5603B
Policy No.		Coverage (\$)	0.00
Claim No.	S2M041M4	Excess (\$)	0.00
Assign From	ONG KIAN THENG DERICK KHOR SAW THENG	Assign Date	20/05/2022 27/09/2022

2. Vehicle Particulars & Condition

Make & Model		c.c	0
Engine No.	HIDDEN	Year of Reg.	
Chassis No.		Colour	
Odometer	-	Steering	
Brakes		Modification	
General			

3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre			mm
L/H Front Tyre			mm
R/H Rear Tyre			mm
L/H Rear Tyre			mm

4. Description of Damages

--	--

5. General Information

Accident Date	17/05/2022	Inspection Date	20/05/2022
Survey held at	(2 Kaki Bukit Avenue 2 #01-33, Kaki Bukit Autohub)		
Repairer	WILLIAM LEE CAR AIR CON ENGINEERING		

5a. Remarks

A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. B) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.
