

# TwinCar AUTOMOTIVE PTE LTD

Kaki Bukit AutoHub  
 2 Kaki Bukit Ave 2  
 #01-17 / #01-18 / Heavy Vehicle #01-08 / Spray Painting #02-27  
 Singapore 417921 Tel No. : +65 6842 0051 Fax No. : +65 6741 0510  
 E-Mail : sales@n51.com.sg  
 Company Reg. No. : 200714616M  
 GST Registration No. : 200714616M

GOKULAMURALI S/O HARIDAS  
 97 LORONG H TELOK KURAU #03-02  
 SINGAPORE 426117

Contact : 96374809

*TP China*  
*Caline*

## TAX INVOICE

Repair Code : CLM15671  
 Date in : 26/09/2022  
 Vehicle Num. : SMY8634H  
 Model : TOYOTA LEXUS IS250C AUTO LUXURY  
 Chassis/Eng# : JTHFK252702514716/4GR0693621

### Parts and Labour Assesment

Description of part	Qty	Unit Price	Amount
REAR BUMPER (507.) <i>Deband</i>	1	1007.10	<del>500(SW)</del> 1,007.10
REAR BUMPER INNER SPONGE <i>ambd</i>	1	128.00	✓ 128.00
REAR BUMPER REINFORCEMENT <i>New</i>	1	475.70	X 475.70
REAR BUMPER REVERSE SENSOR <i>Rygd. id</i>	2	491.50	<del>600</del> 983.00
REAR BUMPER REVERSE SENSOR COVER <i>New</i>	2	56.50	<del>50</del> 113.00
REAR BUMPER SIDE RETAINER L/R <i>New</i>	2	53.70	X 107.40
REAR END PANEL <i>New</i>	1	869.30	X 869.30
Subtotal before discount			3,683.50
Percentage discount 10%			368.35
<b>Sub-total 1</b>			3,315.15
REAR BUMPER CLIPS - SET <i>New</i>	1	50.00	<del>30</del> 50.00
REAR END PANEL TRIM COVER CLIPS - SET <i>New</i>	1	40.00	X 40.00
Subtotal before discount			90.00
Percentage discount 0%			0.00
<b>Sub-total 2</b>			90.00
<b>Parts-total</b>			<b>3,405.15</b>

### LABOUR

To reset system after repair works X 250.00

To remove, reinstall electrical wiring harness, check lighting and rewire for parking sensor. ~~40~~ 60.00

\*\*\* This is a computer-generated document which requires no signature.\*\*\*

Kaki Bukit AutoHub  
 2 Kaki Bukit Ave 2  
 #01-17 / #01-18 / Heavy Vehicle #01-08 / Spray Painting #02-27  
 Singapore 417921 Tel No. : +65 6842 0051 Fax No. : +65 6741 0510  
 E-Mail : sales@n51.com.sg  
 Company Reg. No. : 200714616M  
 GST Registration No. : 200714616M

GOKULAMURALI S/O HARIDAS  
 97 LORONG H TELOK KURAU #03-02  
 SINGAPORE 426117

Contact : 96374809

**TAX INVOICE**

Repair Code : CLM15671  
 Date in : 26/09/2022  
 Vehicle Num. : SMY8634H  
 Model : TOYOTA LEXUS IS250C AUTO LUXURY  
 Chassis/Eng# : JTHFK252702514716/4GR0693621

To remove, reinstall roof top trim upholstery, cushion seat, trim garnish, trim liner carpet. (to FR)	X 80.00
To re-spray painting on the change bodyparts, repair portion, and where consistent to the accident.	440 <del>200</del> 500.00
To provide labour, workmanship to change the above damaged bodyparts, repair, re-construct and re-align body structure, body alignments and damaged consistent to the accident.	<del>200</del> 600.00
To apply anti-rust chemical on repaired and replaced panel.	X 40.00
<b>Labour Total</b>	<b>1,530.00</b>
<b>Parts &amp; Labour Total</b>	<b>4,935.15</b>

\*\*\* This is a computer-generated document which requires no signature.\*\*\*  
 page 2

Total: 1670.20  
 4/s: 1.3K  
 02 Days.

**LKK Auto Consultants** hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer  
 Signature:  
 Date:

1.3K