

China Taiping Insurance (Singapore) Pte. Ltd
3 Anson Road #16-00 Springleaf Tower
Singapore 079909
Tel: 6389 6111

Date: 26/9/2022

RE: MOTOR CLAIM: TP CLAIM

REG. NO
INSURED
MODEL
CHASSIS NO
POLICY NUMBER
EXCESS
D.O.A.

: SKL2666Y
: SOH KIAN WAH DERRICK
: ALFA ROMEO GIULIA SUPER
: ZAREAELNXX7616280
: SP2001604836
:
: 16/09/2022

S/NO	PARTS REPLACEMENT	QTY	LIST PRICE	NETT PRICE	NETT TOTAL
1	REAR BUMPER	1	\$ 1,706.09	\$ 1,364.87	\$ 1,364.87
2	REAR DIFFUSER	1	\$ 1,718.69	\$ 1,374.95	\$ 1,374.95
3	REAR BUMPER CLIPS	2	\$ 2.91	\$ 2.33	\$ 4.66
4	REAR BUMPER BRACKET LHS	1	\$ 100.47	\$ 80.38	\$ 80.38
5	REAR BUMPER BRACKET RHS	1	\$ 96.97	\$ 77.58	\$ 77.58
6	REAR BUMPER REAR CENTRE BRACKET	1	\$ 180.25	\$ 126.18	\$ 144.20
7	REAR BUMPER SENSORS	4	\$ 104.44	\$ 83.55	\$ 334.20
8	REAR BUMPER SENSORS RING	4	\$ 11.70	\$ 9.36	\$ 37.44
9	REAR BUMPER SENSORS WIRE	1	\$ 206.97	\$ 165.58	\$ 165.58
10	REAR CROSSRAIL	1	\$ 692.81	\$ 554.25	\$ 554.25
SubTotal Parts					\$ 4,138.11

S/NO	LABOUR	
1	LABOUR TO REMOVE & REPLACE REAR BUMPER	\$1,000.00
2	LABOUR TO REMOVE & REPLACE REAR DIFFUSER	\$1,000.00
3	LABOUR TO SPRAY FRONT BUMPER	\$1,000.00
4	TO REMOVE & REPLACE REAR PARKING SENSORS	\$1,000.00
5	TO REMOVE & REPLACE REAR PARKING SENSORS WIRE	\$1,000.00
6	TO CONDUCT PRE/POST DIAGNOSTIC CHECK	\$800.00
SubTotal Labour		\$5,800.00

Cost of Repair

Parts \$4,138.11
Labor \$5,800.00
Sub Total \$9,938.11
Total W/GST \$10,633.78

Surveyed by: _____

Contact No: _____

Surveyed date: _____

Excess: _____

Authorised on: _____

Resurvey: _____

Special Nett

Total exclude GST: _____

Yours faithfully,

LKK Auto Consultants hence notify the Repairer of the following:
• To resurvey before/after spray painting
• To display damaged parts during resurvey
• Parts prices are subject to confirmation
• Third party survey is on "Without Prejudice" basis
• No illegal modification(s) is allowed
• Supplemental claim(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature: _____

Date: _____

assignments @ LKKauto.com

6241 1972

Jes