



ASS. REC. BY: Kenneth REF: CTZ/220095261k9

ASSIGNMENT

From: _____ Date: _____
Estimated Cost: _____
OD/TP/WS/TP RES/OD RES/EVA/INV/MV
To Inspect Vehicle No: _____
at Workshop m/s LM Ave
of 8542
Insured: _____
Policy No. _____
Claims No. _____
Sum Insured: _____ Excess: _____
(Client's Record)
Make of Veh: _____
(Policy Condition)
Remark: The veh had commenced its repair at the time of inspection.

Bal. or Market Value: _____
IDAC Accident Rpt: _____ Consistent?: Yes or No
GIA / PR Seen: _____ Consistent?: Yes or No
Est. Repairs: 04 days Res.: Yes or No
Lum Sum: 20 % 3 Val.: Yes or No
CA / REV / REP. / 24 HRS
Date: _____ Person Contacted: _____ Vehicle: IN / OUT

Date / Time _____ Action / Instruction _____

Front
R/Bal. 7 mm
L/Bal. 7 mm
D.O.A. 16/9/22
Survey held at _____
Des. of Damages: Frt / Rear / O/S / N/S / UIC / Rooftop or
N/S
The UIC / Chassis frame / Body Structure affected due to collision.

Veh No: SLK 85062 Yr Regn: 01, 17
Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /
Truck / Trailer or CA
Make: Porsche Macan c.c. 1481
Colour: White A/C: Insured / Std / NI / NA
Sp. Reading: 123953 T/Radio: Insured / Std / NI / NA
Eng/No: _____
C/No: VFIRF B00156 020388
Gen. Cond: Good / Fair / Poor / Burnt
Steering: In order / Jammed / Leaked / Burnt or
Brake: In order / Jammed / Leaked / Burnt or
Mod: NI / S/Rlm / STD A/Rlm or
Tyre Size: F: 225/45 R17
R: _____
BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /
TOYO / YOKO or _____

Rear
R/Bal. 7 mm
L/Bal. 7 mm
D.O.I. 28/9/2022

File Pass to? ☐ : Prell. Report
File Return to? ☐ : Final Report

Days Of Repair: _____
Resurvey No. of Trip: _____

Add Fee: ☐ : Site Insp (\$ _____)
☐ : Interview (\$ _____)
☐ : Tech Invs (\$ _____)
☐ : Weekend (\$ _____)

Survey Fee: _____
Transportation: _____
S - RS. \$ _____
Fuel \$ _____
Others _____
TOTAL _____

Format: _____
n / I.B.I: (\$ _____)

Not Authorise
 11 May 8
 Repair After Paint
 4 days

LM AUTO SOLUTION PTE LTD

Blk 10 Sin Ming Industrial Estate Sector C,
 #01-12 Singapore 575645
 Email: admin@lmautosolution.com
 Tel: 90162222

VEHICLE NUM:

MAKE & MODEL:

MILEAGE:

ENGINE NUM:

CHASSIS NUM:

SLK 8506 E

RENAULT MEGANE

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and described to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

ATTN:	NO.	QTY	PRICE	
	1 FRONT BONNET	1	REPAIR	
	2 FRONT BUMPER	1	\$ 1,867.00	✓
	3 FRONT BUMPER RETAINER LH + RH	2	\$ 164.00	✓
	4 FRONT BUMPER BRACKET LH + RH	2	\$ 182.00	X
	5 FRONT BUMPER REINFORCEMENT	1	\$ 465.00	?
	6 FRONT BUMPER SPONGE	1	\$ 155.00	?
	7 FRONT BUMPER GRILLE LH	1	\$ 126.00	?
	8 FRONT BUMPER CLIP (SET)	1	\$ 80.00	✓
	9 FRONT GRILLE ASSY	1	\$ 858.00	X
	10 FRONT GRILLE CLIP (SET)	1	\$ 60.00	X
	11 FRONT FENDER LH	1	\$ 963.00	✓
	12 FRONT FENDER COWLING LH	1	\$ 189.00	✓
	13 FRONT FENDER GARNISH LH	1	\$ 67.00	?
	14 HEADLAMP ASSY LH	1	\$ 2,986.00	✓
	SUBTOTAL		\$ 8,162.00	
	5%		\$ 408.10	
	PARTS TOTAL		\$ 7,753.90	
	SPECIAL NETT	QTY	PRICE	
	1 FRONT RIM LH	1	\$ 800.00	X
	SPECIAL NETT		\$ 800.00	
	LABOUR	QTY	PRICE	
	1 TO KNOCK, STRAINHTEN AND REALIGN ACCIDENT AFFECTED AREA	1	\$ 600.00	4001
	2 TO PUTTY AND RESPRAY ACCIDENT AFFECTED AREA	1	\$ 800.00	4401
	3 TO RUST PROOF ACCIDENT AFFECTED AREA	1	\$ 60.00	301
	4 TO CHECK WIRING LAYOUT AND HEADLAMP FOCUS	1	\$ 100.00	201
	5 TO CHECK WHEEL ALIGNMENT	1	\$ 100.00	601
	LABOUR TOTAL		\$ 1,660.00	
	GRAND TOTAL COST		\$ 10,213.90	