

MODERN AUTOMOTIVE PTE LTD
BLK 3023A UBI ROAD 1 # 01-61
SINGAPORE 408717

Tel : 6748 4422/ 6745 4422 Fax : 6747- 6720 REG NO 200501102H

CHINA TAIPING INSURANCE (SINGAPORE) PTE LTD

3 Anson Road #16-00
 Springleaf Tower
 Singapore 079909
 Tel : 6389 - 6111
 Fax : 6224 - 7478 / 7175

Xin Yu.

Quotation
 DATE : 27.09.2022
 VEH NO : SGC3333X
 MODEL : Mercedes E200
 D O A : 26.09.2022
 YR REF : YP8424C

Attn : Motor Claim Dept (Pls arrange vehicle survey & check liability)

RE : ESTIMATE FOR ACCIDENT REPAIR SGC3333X (MERCEDES E200)

<u>Item</u>	<u>Description</u>	<u>Qty</u>	<u>Amt</u>
NO	LIST ITEMS		
1	Rear Number Plate Lamp - LH & RH <i>could</i>	2	150.00 ✓
2	Rear Number Plate Lamp Garnish <i>could</i>	1	68.00 ✓
3	Rear Bumper <i>Distorted</i>	1	1,874.00 ✓
4	Rear Bumper Side Holder - LH & RH <i>new</i>	2	384.00 ✓
5	Rear Bumper Reflector - LH & RH <i>Rlt int.</i>	2	138.00 <i>69.</i>
6	Rear Bumper Reinforcement <i>Replaced</i>	1	846.00 ✓
7	Rear Bumper Lower Garnish <i>Distorted</i>	1	485.00 ✓
8	Rear Bumper Lower Garnish Chrome Moulding <i>could</i>	1	291.00 ✓
9	Rear Bumper Exhaust Chrome - LH & RH <i>new</i>	2	462.00 <i>+</i>
10	Rear Bumper Tow Cover <i>Replaced</i>	1	59.00 ✓
11	Rear Bumper Centre Guide <i>Damaged</i>	1	275.00 ✓
12	Rear Bumper Lower Kick Sensor <i>Damaged</i>	1	316.00 ✓
13	Rear Bumper Lower Kick Sensor Bracket - LH & RH <i>new</i>	2	124.00 <i>+</i>
14	Rear Bumper Reverse Sensor <i>3 pieces damaged</i>	4	1,072.00 <i>804.</i>
15	Rear Bumper Reverse Sensor Holder <i>new</i>	4	100.00 ✓
16	Rear Bumper Reverse Sensor Wire Harness <i>new</i>	1	622.00 <i>+</i>
17	Rear End Panel <i>Distorted</i>	1	1,302.00 ✓
18	Rear End Panel Top Cover <i>Replaced</i>	1	229.00 ✓
19	Taillamp - LH & RH <i>could</i>	2	1,570.00 ✓
20	Taillamp Panel - LH & RH <i>Rlt Replaced</i>	2	584.00 <i>292</i>
21	Taillamp Lower Bracket - LH & RH <i>could</i>	2	134.00 ✓
22	Bootlid <i>Distorted</i>	1	2,399.00 ✓
23	Bootlid Lock <i>Jammed</i>	1	294.00 ✓
24	Bootlid Lock Actuator <i>Damaged</i>	1	489.00 ✓
25	Bootlid Weatherstripe <i>lt</i>	1	292.00 ✓
26	Bootlid Hinge - LH & RH <i>Best</i>	2	570.00 ✓
27	Bootlid Hinge Cover - LH & RH <i>Replaced</i>	2	116.00 ✓
28	Bootlid Inner Trim Board <i>Replaced</i>	1	525.00 ✓

RE : ESTIMATE FOR ACCIDENT REPAIR SGC3333X (MERCEDES E200)

29	Bootlid Inner Garnish Cover	<i>new</i>	1	275.00	<i>X</i>
30	Bootlid Outer Chrome Moulding	<i>new</i>	1	267.00	<i>✓</i>
31	Bootlid Opener Switch	<i>new</i>	1	198.00	<i>✓</i>
32	Bootlid Camera	<i>new</i>	1	859.00	<i>✓</i>
33	Mercedes Benz Logo	<i>new</i>	1	70.00	<i>✓</i>
34	E200 Wording	<i>new</i>	1	93.00	<i>✓</i>
35	9G Tronic Wording	<i>new</i>	1	97.00	<i>✓</i>
36	Rear Fender - RH	<i>Distorted</i>	1	1,849.00	<i>✓</i>
37	Rear Fender Inner Trim Board - LH & RH	<i>RH Del'd</i>	2	910.00	<i>455</i>
38	Rear Fender Top Garnish - LH & RH	<i>LH new, RH ut</i>	2	104.00	<i>✓</i>
39	Rear Windscreen	<i>ut</i>	1	1,281.00	<i>✓</i>
40	Rear Windscreen Moulding	<i>new</i>	1	254.00	<i>✓</i>
41	Spare Tyre Panel (Fibre)	<i>new</i>	1	498.00	<i>X</i>
42	Spare Tyre Panel Top Board	<i>Del'd</i>	1	710.00	<i>✓</i>
43	Spare Tyre Panel Carpet	<i>Del'd</i>	1	595.00	<i>✓</i>
44	Spare Tyre Panel Sponge Tray	<i>new</i>	1	158.00	<i>X</i>
45	Front Driver Seat Belt	<i>Activated</i>	1	868.00	<i>✓</i>
46	Front Passenger Seat Belt	<i>Activated</i>	1	868.00	<i>✓</i>
47	Rear Passenger Seat Belt	<i>2 pieces Activated</i>	3	2,001.00	<i>1334</i>
48	Air Bag ECU	<i>Activated</i>	1	915.00	<i>✓</i>

24750

22275

Less *10%*
~~20%~~

\$	28,640.00
	(5,728.00)
\$	22,912.00

S/NETT ITEMS

1	Rear End Panel Top Garnish Clips	<i>new</i>	1 set	20.00	<i>✓</i>
2	Rear End Panel Sealant	<i>new</i>	1	60.00	<i>✓</i>
3	Rear Number Plate	<i>Best</i>	1	30.00	<i>✓</i>
4	Rear Number Plate Holder	<i>Del'd</i>	1	30.00	<i>✓</i>
5	Rear Bumper Clips	<i>new</i>	1 set	50.00	<i>✓</i>
6	Rear Bumper Lower Garnish Clips	<i>new</i>	1 set	20.00	<i>✓</i>
7	Bootlid Inner Trim Board Clips	<i>new</i>	1 set	30.00	<i>✓</i>
8	Bootlid Inner Garnish Cover Clips	<i>new</i>	1 set	20.00	<i>✓</i>
9	Bootlid Outer Chrome Moulding Clips	<i>new</i>	1 set	20.00	<i>✓</i>
10	Rear Fender Inner Trim Board Clips	<i>new</i>	1 set	100.00	<i>30</i>
11	Rear Fender Top Garnish Clips	<i>new</i>	1 set	40.00	<i>✓</i>
12	Rear Windscreen Sealant	<i>new</i>	1	60.00	<i>✓</i>
13	Rear Windscreen Solar Film	<i>new</i>	1	300.00	<i>250</i>
14	Hazard Sign Set	<i>new</i>	1	280.00	<i>200</i>

Total parts

\$ 23,972.00

LABOUR CHARGE

- 1 To knocking out rear portion & renew above parts

\$ 2,200.00 *1700*

RE : ESTIMATE FOR ACCIDENT REPAIR SGC3333X (MERCEDES E200)

2	To putty & spray up paint works	\$	2,000.00 1400.
3	To check wiring	\$	100.00 50
4	To apply tuff coat	\$	150.00 100.
5	To remove reverse sensor	\$	100.00 60.
6	To remove rear camera	\$	100.00 60
7	To remove rear video recorder	\$	100.00 60
8	To remove upholstery	\$	150.00 80.
9	To transfer bootlid fittings	\$	150.00 80.
10	To remove rear windscreen	\$	180.00 120
11	To remove front and rear seat belts	\$	500.00 350.
12	To reset air bag settings	\$	500.00 280
13	To perform diagnostic test	\$	400.00 200.

Total Labour \$ 6,630.00

Grand Total \$ 30,602.00

GST Will be reflected in the final bills

NOTE : -

PLEASE INFORM US WITHIN 14 DAYS, FROM THE DATE OF THIS LETTER, IN THE EVENT THAT THE OWNER/DRIVER IS IN BREACH OF ITS POLICY WITH YOUR COMPANY, FAILING WHICH WE SHALL HOLD YOUR COMPANY LIABLE FOR ALL COSTS OF REPAIRS, LOSS OF USE AND STORAGE.

total: 27675
h/s: 22.11.12.

10 Days.

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: