

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com;cs-a@lkkauto.com;admin-a@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORTAIG Asia Pacific Insurance Pte. Ltd.
AIG Building, 78 Shenton Way, #09-16
Singapore 079120**Our File No:** CC3/AIG22009532/ACE2**Date:** 05/07/2023**REFERENCE**

Insured/Claimant:	ZHANG LING	Policy No:	2070107971-02	
Date of Loss:	22/09/2022	Nature of Claim:	OD	Claim No: 6325432907SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SMT8483C		
Make & Model:	AUDI Q2, 999cc 1.0 TFSI S TRONIC (A)	Engine No:	CHZC35611
Reg. Date:	21/07/2020 (Man. Year: 2019)	Chassis No:	WAUZZZGA6LA002475
Colour:	Red	Odometer:	44705 km
Engine Capacity:	999 cc		
Market Value/New Car Price:	S\$128,000.00		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	215/60 R16	Rear Tyre Size:	215/60 R16
Front Left Side:	Bridgestone 6 mm	Rear Left Side:	Bridgestone 6 mm
Front Right Side:	Bridgestone 6 mm	Rear Right Side:	Bridgestone 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	5,360.00	2,824.00	2,536.00	47.31
Miscellaneous Items	0.00	0.00	0.00	
Labour	6,272.00	2,322.00	3,950.00	62.98
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	11,632.00	5,146.00	6,486.00	55.76
- Excess (S\$)	800.00	800.00	0.00	0.00
(S\$)	10,832.00	4,346.00	6,486.00	59.88
+ GST 8.00/8.00% (S\$)	866.56	347.68	518.88	59.88
Nett Amount (S\$)	11,698.56	4,693.68	7,004.88	59.88

INSPECTION

Date of Assignment:	28/09/2022		
Date Inspected:	27/09/2022	Inspected At:	Premium Automobiles Pte Ltd (UBI) 55 Ubi Road 1 Singapore 408699
Estimated Period of Repair:	4.0 days		

Adjuster: ADRIAN LING**Manager:** CELINE FONG*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR DOOR - LH	Dented	2,962.00 FS	*2,369.60 FS
2	1		*REAR OUTER DOOR SEAL - LH	Necessary	151.00 FS	*120.40 FS
3	1		*BONDING AGENT	Not Necessary	51.00 FS	*- FS
4	1		*CLEANING SOLUTION	Not Necessary	74.00 FS	*- FS
5	1		*APPLICATOR	Not Necessary	9.00 FS	*- FS
6	1		*REAR DOOR CATCH - LH	Not Necessary	134.00 FS	*- FS
7	1		*REAR WINDOW REGULATOR - LH	Not Necessary	302.00 FS	*- FS
8	1		*REAR DOOR COVER - LH	Deformed	238.00 FS	*190.40 FS
9	1		*FRONT DOOR COVER - LH	Not Necessary	270.00 FS	*- FS
10	1		*REAR WHEEL COVER - LH	Cut	180.00 FS	*143.60 FS
11	1		*REAR WINDOW APERTURE SEAL - LH OUTER	Not Necessary	151.00 FS	*- FS
12	1		*REAR FIXED WINDOW SEAL - LH	Not Necessary	350.00 FS	*- FS
13	1		*REAR UNDERBODY TRIM - LH	Not Necessary	188.00 FS	*- FS
14	1		*SUNDRIES	Not Necessary	300.00 FS	*- FS

F=Franchise part. S=SpcNett.

Total Parts (S\$)	5,360.00	2,824.00
--------------------------	-----------------	-----------------

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO REMOVE AND REINSTALL LHS FRONT DOOR WING MIRROR ASSY	New	280.00	0.00
2	TO DISMANTLE AND RENEW LHS REAR DOOR. REPAIR LHS REAR FENDER. REINSTALL ALL PARTS REMOVED	New	2,400.00	750.00
3	TO CARRY OUT DIAGNOSTIC CHECK	New	192.00	192.00
4	TO REMOVE AND TRANSFER LHS REAR DOORS MULTI-LOCK SYSTEM AND POWER WINDOW DEVICES. INSPECT FOR DAMAGES	New	400.00	280.00
5	TO RESPRAY LHS FRONT AND REAR DOORS, AND LHS REAR FENDER	New	3,000.00	1,100.00
Gross Labour Cost (\$\$)			6,272.00	2,322.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >