

55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

ESTIMATE : ACCIDENT REPAIRS
WORKSHOP : UBI ROAD 1
CONTACT NO : 6366 2323
FAX NO : 6841 1183
REFERENCE : PA/OD/0822/2022/EQ
DATE : 23-Sep-22
WIP : 43017

VEHICLE NOT IN WORKSHOP. KINDLY ARRANGE FOR SURVEY ON 27/09/2022

AIG ASIA PACIFIC INSURANCE PTE LTD

78 SHENTON WAY

#07-16 AIG BUILDING

SINGAPORE 079120

Attn: Motor Claims Dept

Tel: 6880 4602 - Fax: 6880 4838

OWNER'S NAME : MS ZHANG LING
ADDRESS : BLK 709 ANG MO KIO
#01-2597
SINGAPORE 560709
TELEPHONE : HP +65 96890345
TYPE OF CLAIM : OWN DAMAGE CLAIM
POLICY NO : 2070107971-02
VEHICLE NO : **SMT 8483 C**
MODEL CODE : AUDI Q2 1.0 TFSI S-TRONIC
MODEL YEAR : 21/7/2020
ENGINE NO : CHZ C35611
CHASSIS NO : WAUZZZGA6LA002475
MILEAGE : -
DATE IN : -
ESTIMATED BY : JOHNNY BOO / ALLAN WU
ACCIDENT DATE : 22-Sep-22
PLACE OF ACCIDENT : BLK 712 MULTI STOREY CARPARK ANG MO KIO

55 UBI ROAD 1, SINGAPORE 408699
 TEL : 6366 2323 FAX : 6841 1183
 EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

ESTIMATED LABOUR CHARGES FOR ACCIDENT VEHICLE SMT 8483 C

S/N	NATURE OF JOBS	ESTIMATED CHARGES	SURVEYOR'S RECOMMENDATIONS
1	TO REMOVE AND TRANSFER LHS REAR DOOR'S MULTI-LOCK SYSTEM AND POWER WINDOW DEVICES. INSPECT FOR DAMAGES. S/N \$	400.00 <i>280</i>	
2	TO REMOVE AND REINSTALL LHS FRONT DOOR WING MIRROR ASSY. S/N \$	280.00 <i>X</i>	
3	TO DISMANTLE AND RENEW LHS REAR DOOR. REPAIR LHS REAR FENDER. REINSTALL ALL PARTS REMOVED. \$	2,400.00 <i>500</i>	<i>885.</i> <i>750.00</i>
4	TO RESPRAY LHS FRONT AND REAR DOORS, AND LHS REAR FENDER. \$	3,000.00 <i>1100</i>	
5	TO CARRY OUT DIAGNOSTIC CHECK S/N \$	192.00 <i>✓</i>	
TOTAL LABOUR CHARGES		: \$ 6,272.00	

55 UBI ROAD 1, SINGAPORE 408699
TEL : 6366 2323 FAX : 6841 1183
EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SMT 8483 C

DAMAGED PARTS & PRICES

S/N	PARTS DESCRIPTION	QTY	S/NETT	REMARKS
1	REAR DOOR - LH <i>Dented</i>	1	\$ 2,962.00 ✓	2369.60
2	REAR OUTER DOOR SEAL - LH <i>new</i>	1	\$ 151.00 ✓	120.40
3	BONDING AGENT	1	\$ 51.00 ? X	
4	CLEANING SOLUTION	1	\$ 74.00 ? X	
5	APPLICATOR	1	\$ 9.00 ? X	
6	REAR DOOR CATCH - LH	1	\$ 134.00 ? X	
7	REAR WINDOW REGULATOR - LH ?	1	\$ 302.00 ? X	
8	REAR DOOR COVER - LH <i>Delaid</i>	1	\$ 238.00 ✓	190.40
9	FRONT DOOR COVER - LH <i>new</i>	1	\$ 270.00 X	
10	REAR WHEEL COVER - LH <i>new</i>	1	\$ 180.00 ✓	143.60
11	REAR WINDOW APERTURE SEAL - LH OUTER <i>new</i>	1	\$ 151.00 ✓	
12	REAR FIXED DOOR WINDOW SEAL - LH <i>new</i>	1	\$ 350.00 ✓	
13	REAR UNDERBODY TRIM - LH <i>new</i>	1	\$ 188.00 ✓	
14	SUNDRIES <i>new</i>		\$ 300.00 ? X	
TOTAL SPARE PARTS		:	\$ 5,360.00	
TOTAL LABOUR CHARGES		:	\$ 6,272.00	
GRAND TOTAL		:	\$ 11,632.00	

ALL CHARGES ARE NOT INCLUSIVE OF GST

LEGEND: REMARKS (OK) = APPROVED, REMARKS (X) = NOT APPROVED
SPARE PARTS ARE SPECIAL NETT.



55 UBI ROAD 1, SINGAPORE 408699
TEL : 6366 2323 FAX : 6841 1183
EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

NAME : *Adrian L*
SURVEYED DATE : *27/09/22*
AUTHORISED DATE :
EXCESS COST :
LIABILITY :
REMARKS : *Not Authorised, 04 Day*

PLEASE NOTE : THIS ESTIMATE IS BASED ON VISUAL INSPECTION OF THE AFFECTED VEHICLE. SHOULD WE REQUIRE FURTHER LABOUR CHARGES AND SPARE PARTS IN THE PROGRESS OF REPAIR, WE SHALL INFORM YOU ACCORDINGLY. FOR INSPECTION OF VEHICLE, PLEASE REFER TO MS. NORAH KHAI AT TEL: 6768 9828 / 6768 9911 FOR APPOINTMENT.

YOURS FAITHFULLY,
PREMIUM AUTOMOBILES PTE LTD

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date:

JOHNNY BOO
BODY REPAIR MANAGER

ALLAN WU
CLAIMS CONSULTANT