



# HS AUTOMOTIVES PTE LTD

Blk 2 KAKI BUKIT AVE 2 @ KAKI BUKIT AUTOHUB #02-25 SINGAPORE 417921.  
TEL: 6538 1368 FAX: 6538 1367 EMAIL: HSAUTOMOTIVESPL@GMAIL.COM  
ROC: 201907812C

INDEPENDENT SURVEYOR

DIRECT SETTLEMENT

WORK SHOP REPAIRER ESTIMATE

Date: 27-9-20

Vehicle No :

8LZ5018

Make/Model :

AUD A6

CHASSIS NO :

WAUZZZ14624ND022900

MARKING

UNIT \$

AMOUNT (\$\$)

Estimate cost of repair to the above mentioned

NO. QTY List Items

|    |   |                                  |         |   |    |     |   |            |
|----|---|----------------------------------|---------|---|----|-----|---|------------|
| 1  | 1 | LH FRONT HEAD LAMP               | Good    | ✓ | \$ | -   | ✓ | \$ 1047.00 |
| 2  | 1 | LH FRONT HEAD LAMP LOWER BRACKET | NEW     | ✓ | \$ | -   | X | \$ 131.50  |
| 3  | 1 | LH FRONT FENDER                  | Buckled | ✓ | \$ | -   | ✓ | \$ 1500.00 |
| 4  | 1 | LH FRONT FENDER INNER SHIELD     | NEW     | X | \$ | -   | X | \$ 310.00  |
| 5  | 1 | LH FRONT FENDER SHIELD CLIP      | NEW     | X | \$ | SET | X | \$ 195.00  |
| 6  | 1 | FRONT BUMPER                     | Good    | ✓ | \$ | -   | ✓ | \$ 3475.00 |
| 7  | 1 | FRONT BUMPER CLIP                | NEW     | ✓ | \$ | SET | ✓ | \$ 170.00  |
| 8  | 1 | LH FRONT BUMPER WASHWATER CAP    | MISS    | ✓ | \$ | -   | ✓ | \$ 63.90   |
| 9  | 1 | LH FRONT HEAD LAMP NOZZLE        | Good    | ✓ | \$ | -   | ✓ | \$ 259.00  |
| 10 | 1 | LH FRONT BUMPER BARNISH          | NEW     | ✓ | \$ | -   | ✓ | \$ 355.00  |
| 11 | 1 | FRONT RADIATOR GRILLE            | NEW     | ✓ | \$ | -   | X | \$ 2140.00 |
| 12 | 1 | LH FRONT PARKING SENSOR          | NEW     | ✓ | \$ | -   | ✓ | \$ 265.50  |
| 13 | 1 | FRONT SUPPORT PANEL              | NEW     | + | \$ | -   | X | \$ 1385.00 |
| 14 | 1 | LH FRONT BUMPER RETAINER         | NEW     | + | \$ | -   | X | \$ 21.40   |
| 15 | 1 | LH FRONT BUMPER BRACKET          | NEW     | ? | \$ | -   | ✓ | \$ 105.00  |
| 16 |   |                                  |         |   | \$ | -   |   | \$ -       |
| 17 |   |                                  |         |   | \$ | -   |   | \$ -       |
| 18 |   |                                  |         |   | \$ | -   |   | \$ -       |
| 19 |   |                                  |         |   | \$ | -   |   | \$ -       |
| 20 |   |                                  |         |   | \$ | -   |   | \$ -       |

REMARKS:

NO OF DAYS:

AGREED FIGURE/LUMP SUM:

\$ -

SURVEYOR NAME

CONTACT:

EMAIL ADD:



# HS AUTOMOTIVES PTE LTD

Blk 2 KAKI BUKIT AVE 2 @ KAKI BUKIT AUTOHUB #02-25 SINGAPORE 417921.  
TEL: 6538 1368 FAX: 6538 1267 EMAIL: HSAUTOMOTIVESPL@GMAIL.COM  
ROC: 201907812C

INDEPENDENT SURVEYOR

DIRECT SETTLEMENT

WORK SHOP REPAIRER ESTIMATE

Vehicle No :

8275018

Make/Model :

AUDI A6

CHASSIS NO :

Date:

Estimate cost of repair to the above mentioned

MARKING

UNIT \$

AMOUNT (\$\$)

NO. QTY List Items

|    |  |                      |    |   |         |
|----|--|----------------------|----|---|---------|
| 1  |  | PAINT BODY           | \$ | - | \$ 1200 |
| 2  |  |                      | \$ | - | \$ 400  |
| 3  |  | SPRAY PAINT          | \$ | - | \$ 1200 |
| 4  |  |                      | \$ | - | \$ 30   |
| 5  |  | CHECK WIRING         | \$ | - | \$ 100  |
| 6  |  |                      | \$ | - | \$ 120  |
| 7  |  | REPROGRAM PDA SYSTEM | \$ | - | \$ 100  |
| 8  |  |                      | \$ | - | \$ -    |
| 9  |  | RUST PROOF.          | \$ | - | \$ -    |
| 10 |  |                      | \$ | - | \$ -    |
| 11 |  |                      | \$ | - | \$ -    |
| 12 |  |                      | \$ | - | \$ -    |
| 13 |  |                      | \$ | - | \$ -    |
| 14 |  |                      | \$ | - | \$ -    |
| 15 |  |                      | \$ | - | \$ -    |
| 16 |  |                      | \$ | - | \$ -    |
| 17 |  |                      | \$ | - | \$ -    |
| 18 |  |                      | \$ | - | \$ -    |
| 19 |  |                      | \$ | - | \$ -    |
| 20 |  |                      | \$ | - | \$ -    |

REMARKS:

NO OF DAYS:

AGREED FIGURE/LUMP SUM:

\$ -

SURVEYOR NAME

EMAIL ADD:

LKK Auto Consultants hence notify  
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: