

Note: This document has not been finalised.**LKK Auto Consultants Pte Ltd** (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

To: MSIG Insurance (Singapore) Pte. Ltd.
4 Shenton Way
#21-01 SGX Centre 2
Singapore 068807

From: LKK Auto Consultants Pte Ltd
51 Ubi Ave 1 #01-25
Paya Ubi Industrial Park
Singapore 408933

Attn: Richard Ang Wei Guang

Date: 07 Feb 2023

Preliminary Advice

Insured Vehicle No	: SLM260E	Accident Date	: 26/09/2022
TP Vehicle No	: SLZ501S	Assignment Date	: 27/09/2022
Make	: AUDI A6	Est. Duration of Repair	: 4
Date of Inspection	: 27/09/2022		
Inspection At	: H S AUTOMOTIVE SERVICES (KAKI BUKIT) BLK 2 KAKI BUKIT, AVENUE 2, # 01-15, KAKI BUKIT AUTOHUB SINGAPORE 417921		

Point of Impact / General Description of Damages

Parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	23,283.30
Revised Amount	:S\$	15,702.36
Check Items (Estimated)	:S\$	0.00
Total	:S\$	15,702.36
 Lump Sum Repair	 :S\$	 12,500.00

Total Loss Consideration

New for Old Value	:S\$
Pre-Accident Value	:S\$
COE / PARF Rebate	:S\$
Salvage Value	:S\$
Margin for Repair	:S\$

Remarks

- () The vehicle is economical for repair
 () The vehicle is not economical for repair
 () Part-by-Part repair
 (x) Lump Sum repair
- () The above survey was conducted on a 'without prejudice' basis. Please note that the preliminary advice amount (Revised & Check Items) stated are subject to consistency check, part prices and labour cost.