

ASS. REC. BY: Marcus

REF:

CS/10522009540/4943

ASSIGNMENT

From: Date:

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: SMF26277
at Workshop m/s Lee brother loan
of

Insured: SJG8494A

Policy No.


Claims No.

Sum Insured: Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.

Bal. or Market Value: \$90k.

IDAC Accident Rpt: Consistent? : Yes or No

GIA / PR Seen: Consistent? : Yes or No

Est. Repairs: 2 days Res.: Yes or No

Lum Sum: 1.3.1 % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

428C

Vehicle: IN / OUT

Date: Person Contacted: L7A4 43728

Veh No:

SMF26277

Yr Regn: 31/10/18

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or CA /

Make:

Peugeot 3008 c.c. 1598

Colour:

Grey A/C: Insured / Std / NI / NA

Sp. Reading:

60959 T/Radio: Insured / Std / NI / NA

Eng/No:

C/No:

VT3M4567WJ5268019

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt or

Brake: Inorder / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size:

F: 225/55 R18

R:

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

Rear

R/Bal.

7 mm

R/Bal.

7 mm

L/Bal.

7 mm

L/Bal.

7 mm

D.O.A.

03/08/22

D.O.I.

29/9/22

Survey held at

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

N/S Body

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

Rep 13k.

Repair done?

31/10/22 P/P 1053-71 informed MA Lee (Ref \$2670.15, 72%)

Date/Time, File Pass to?



: Preli. Report

1) 31/10 turn



: Final Report

Date/Time, File Return to?

2)

Days Of Repair: 2

Resurvey No. of Trip: 1

Survey Fee:

Transportation:

Add Fee:



: Site Insp (\$



: Interview (\$



: Tech. Invs (\$



: Weekend (\$

) \$ + RS, \$ SI

) Photos

) Others

TOTAL

Report Format :

MER-TP

Lump Sum / I.B.I. (\$

1053-71

)

LEE BROTHERS AUTOMOTIVE PTE. LTD.

NO 1 KAKI BUKIT AVE 6 #02-47

AUTOBAY SINGAPORE 417883

Tel : 6509 5521 / 65095524 Fax : 6509 5523

Email: Sales@Leebrothers.com.sg

Vehicle Number: SMF2627T

Vehicle Model: PEUGEOT 3008

PARTICULAR

AMOUNT

QTY

S\$

LIST PRICE

1	FRONT DOOR -LH	<i>R</i>	\$ 1,850.90	<i>X</i>
1	FRONT DOOR PROTECTOR W/MOULDING	<i>scuff</i>	\$ 681.90	<i>/</i>
1	FRONT DOOR W/STRIP	<i>11</i>	\$ 182.60	<i>X</i>
			\$ 2,715.40	
		LESS 10%	\$ 271.54	
			\$ 2,443.86	

SPECIAL NETT ITEMS

<i>1st</i>	FRONT DOOR PROTECTOR CLIP	<i>Net</i>	\$ 80.00	<i>40</i>
			\$ 80.00	

LABOUR CHARGES

TO PUTTY, SPRAY PAINT & POLISH AFFECTED PARTS	\$ 600.00	<i>200</i>
TO PANEL BEAT, CUT, WELD, REMOVE & REPLACE DAMAGED PARTS	\$ 600.00	<i>200</i>
	\$ 1,200.00	

ESTIMATE PARTS AND LABOUR GRAND TOTAL :

\$ 3,723.86

not Affected
like
29/9/22
P/P @ 1053.71
2 days.

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: