

Performance Motors Limited

A Sime Darby Motors Company
Co. Reg. No. 197401559W GST Reg. No M2-0020081-X
Toll-Free Number (1800-2255269)

303, Alexandra Road
Sime Darby Performance Centre
Singapore 159941
Fax. 64747770

280, Kampong Arang Road
East Coast Centre
Singapore 438180
Fax. 63449773

315, Alexandra Road
Sime Darby Business Centre
Singapore 159944
Fax. 64796601 (AfterSales)
64796624 (Motorrad)



GST REG. NO : M2 - 0020081 - X

E S T I M A T E

27 SEP 2022

Estimate No. : b1 63449
Date Estimated : 27/09/2022
Prepared By : Jack Ng Guo Ming

Page No. : 1 of 4

- ESTIMATE REPAIR FOR -

CHEN YONGLIN
161 POH HUAT ROAD WEST
#02-05

SINGAPORE 546692

- ACCOUNT - 40000

Cash Sales - Service
Singapore

REGN. NO.	CHASSIS NO.	REGN. DATE	MODEL	MILEAGE
SMR2536J	WBA2X920X07F16234	27/12/2019	216i Active Tourer	28369

DESCRIPTION

To replace rear bumper.

VALUE

1,700.00

To respray rear bumper.

1,038.00

To remove old PDC assembly, replace damaged parts and
reconnect to new bumper including conduct check for
proper function.

177.00

To check electrical wiring

177.00

Sundries.

150.00

Total Labour 1: 3,242.00

DESCRIPTION

RR BUMPER LH SIDE GUIDE

QTY

PRIC

VALUE

RR BUMPER RH SIDE GUIDE

1

163.55

163.55

SUPPORT

1

163.55

163.55

REAR BUMPER TRIM STRIP (BLACK)

1

47.00

47.00

REAR BUMPER PANEL PRIMED (LINES PDC)

1

90.30

90.30

1,050.55

1,050.55

Total Parts : 1,514.95



Labour 1 : 3,242.00

Parts : 1,514.95

Labour 2 : 0.00

Excess : 0.00

Total GST @ 7% : 332.99

Grand Total : 5,089.94

** THIS ESTIMATE IS VALID FOR A PERIOD OF 30 DAYS ONLY**

** PRICE FOR PARTS ARE SUBJECTED TO CHANGE WITHOUT PRIOR NOTICE **