



## Final Report

Estimate No. : **b1 63449**  
Date Estimated : **27/09/2022**  
Prepared By : **Jack Ng Guo Ming**

Page No. :

**- ESTIMATE REPAIR FOR -**

**CHEN YONGLIN**

**161 POH HUAT ROAD WEST**

**#02-05**

**SINGAPORE 546692**

**- ACCOUNT - 303**

**MS First Capital Insurance Limited**

**6 Raffles Quay**

**#21-00**

**Singapore 048580**

REGN. NO.	CHASSIS NO.	REGN. DATE	MODEL	M LEAGE
<b>SMR2536J</b>	<b>WBA2X920X07F16234</b>	<b>27/12/2019</b>	<b>216i Active Tourer</b>	<b>30115</b>

DESCRIPTION	ORIGINAL PRICE		NETT
To replace rear bumper and attachment include knocking out dents caused by the accident	850.00	0.00	850.00
To respray rear bumper	986.00	0.00	986.00
To remove old PDC assembly, replace damaged parts and reconnect to new bumper including conduct check for proper function	168.00	0.00	168.00
To check electrical wirings system and lightings at the rear section for proper function	168.00	0.00	168.00
Sundries	80.00	0.00	80.00

DESCRIPTION	UNIT PRICE	QTY	DISC. %	NETT
REAR BUMPER TRIM STRIP (BLACK)	90.30	1.00	0.00	90.30
REAR BUMPER PANEL PRIMED (LINES PDC)	1,050.55	1.00	0.00	1,050.55

**# SUPPLEMENTARY ITEMS**

Total Labour :	2,252.00
Total Parts :	1,140.85
Total Labour & Parts :	3,392.85
Deduction for Excess :	
Total Repair Costs less Excess:	3,392.85
GST @7%:	237.50
Grand Total :	3,630.35