

**Main Office:**

Mova Building  
No. 22, Jalan Kilang,  
Singapore 159419  
Tel: (65) 6476 3333  
Fax: (65) 6271 5891  
www.mova.com.sg

**Workshop Dept:**

Block 1008,  
Bukit Merah Lane 3,  
#01-04/06/08/94  
Singapore 159722  
Tel: (65) 6272 3892  
Fax: (65) 6270 8314  
Co. Reg. 198904033G  
GST Reg. M2-0088864-2

**Estimate**

27/09/2022

EQ INSURANCE CO LTD  
5 MAXWELL ROAD  
#17-00 TOWER BLOCK MND COMPLEX  
SINGAPORE 069110

Attention :- XA039

*Steve (LKK)*  
*28/9/22 2-3pm*  
*n n*  
*6 # djs*  
*L/S*  
*to ALY*

Page # :- 1  
Veh # :- SLP1195M  
Veh Model :- TOYOTA ALTIS  
Estimate# :- CK424044  
Claim # :-  
ACC. Date :- 27/09/22  
Terms :- C.O.D Days  
Remarks :-

| No.  | Description                                      | Qty   | U.Price | Amounts S\$         |
|--|--|-------|---------|---------------------|
| <b>LIST ITEMS :</b>  |  |       |         |                     |
| 1.   | REAR BUMPER / <i>DD</i>                          | 1 PC  | 689.50  | 689.50 <i>581 ✓</i> |
| 2.   | REAR BUMPER REINFORCEMENT / <i>BT</i>            | 1 PC  | 423.90  | 423.90 <i>395 ✓</i> |
| 3.   | REAR BUMPER SIDE RETAINER BRACKET LH / <i>PK</i> | 1 PC  | 116.00  | 116.00 ✓            |
| 4.   | REAR BUMPER SIDE RETAINER BRACKET RH / <i>PK</i> | 1 PC  | 116.00  | 116.00 ✓            |
| 5.   | REAR END PANEL / <i>DD</i>                       | 1 PC  | 740.90  | 740.90 ✓            |
| 6.   | REAR END PANEL TOP COVERING / <i>CUT</i>         | 1 PC  | 256.60  | 256.60 <i>202 ✓</i> |
| 7.   | REAR SPARE TYRE UPPER BOARD / <i>X NN</i>        | 1 PC  | 382.80  | 382.80              |
| 8.   | REAR TAIL LAMP RH / <i>X NN</i>                  | 1 PC  | 472.60  | 472.60              |
| 9.   | REAR BOOT LID "COROLLA" EMBLEM / <i>PK</i>       | 1 PC  | 56.50   | 56.50 ✓             |
| 10.  | REAR BOOT LID "ALTIS" EMBLEM / <i>PK</i>         | 1 PC  | 58.30   | 58.30 ✓             |
| 11.  | REAR BOOT LID "LOGO" EMBLEM / <i>PK</i>          | 1 PC  | 80.70   | 80.70 ✓             |
| 12.  | REAR BOOT LID (REPAIR) / <i>X R</i>              | 1 PC  |         |                     |
| 13.  | REAR QUATER PANEL RH (REPAIR) / <i>X R</i>       | 1 PC  |         |                     |
| 14.  | REAR SPARE TYRE PANEL (REPAIR) / <i>X R</i>      | 1 PC  |         |                     |
| LIST TOTAL S\$   |  |       |         | 3,393.80            |
| 25% DISCOUNT S\$ <i>* end of sensor</i>  |  |       |         | -848.45             |
|  |  |       |         | 2,545.35            |
|  |  |       |         | 2442.80             |
|  |  |       |         | -25%                |
|  |  |       |         | 1832.10             |
| <b>SPECIAL NET ITEMS :</b>   |  |       |         |                     |
| 1.   | REAR BUMPER REVERSE SENSOR / <i>Shnd</i>         | 1 PC  | 200.00  | 200.00 ✓            |
| 2.   | REAR BUMPER CLIPS / <i>PK</i>                    | 1 SET | 40.00   | 40.00 <i>30</i>     |
| 3.   | REAR END PANEL TOP COVERING CLIPS / <i>?</i>     | 1 SET | 30.00   | 30.00 <i>10 ✓</i>   |
| 4.   | REAR END PANEL JOINT SEALANT / <i>?</i>          | 1 PC  | 50.00   | 50.00 <i>20 ✓</i>   |
| SPECIAL NET TOTAL S\$  |  |       |         | 320.00 <i>260</i>   |
| <b>LABOUR :</b>  |  |       |         |                     |
| TO REMOVE, REPLACE, REFIT REAR BUMPER, REVERSE SENSOR, REAR REVERSE CAMERA & ETC. TO EFFECT REPLACE OF REAR BUMPER   |  |       |         | <i>30</i> 80.00     |
| TO CHECK WIRING & ELECTRICAL SYSTEM  |  |       |         | <i>30</i> 60.00     |
| TO REMOVE, REPLACE, REPAIR, READJUST & CHISEL REAR ACCIDENT AREAS SUCH AS REAR BOOT LID, REAR END PANEL, REAR BUMPER, REAR SPARE TYRE PANEL, REAR QUATER PANEL RH & ETC. BACK TO ORIGINAL CONDITIONS |  |       |         | <i>400</i> 900.00   |
| TO SUPPLY PAINT & FURNISHING MATERIALS AT REAR BUMPER, REAR END PANEL, REAR BOOT LID, REAR SPARE TYRE PANEL, REAR QUATER PANEL RH & ETC.   |  |       |         | <i>800</i> 1,000.00 |
| LABOUR TOTAL S\$   |  |       |         | total - 3352.10     |
|  |  |       |         | 1260 2,040.00       |
|  |  |       |         | L/S - 2681.68       |
|  |  |       |         | = 2700              |

*bizSAFE*

# Estimate

27/09/2022

**EQ INSURANCE CO LTD**  
**5 MAXWELL ROAD**  
**#17-00 TOWER BLOCK MND COMPLEX**  
**SINGAPORE 069110**

Attention :- **XA039**

Page # :- 1 147126  
Veh # :- SLP1195M  
Veh Model :- TOYOTA ALTIS  
Estimate# :- CK424044  
Claim # :-  
ACC. Date :- 27/09/22  
Terms :- C.O.D Days  
Remarks :-

**Main Office:**  
Mova Building  
No. 22, Jalan Kilang,  
Singapore 159419  
Tel: **(65) 6476 3333**  
Fax: (65) 6271 5891  
www.mova.com.sg

**Workshop Dept:**  
Block 1008,  
Bukit Merah Lane 3,  
#01-04/06/08/94  
Singapore 159722  
Tel: **(65) 6272 3892**  
Fax: (65) 6270 8314  
Co. Reg. 198904033G  
GST Reg. M2-0088864-2

| No. | Description | Qty | U.Price | Amounts S\$ |
|-----|-------------|-----|---------|-------------|
|-----|-------------|-----|---------|-------------|

E. & O.E

NON-TAX AMOUNT S

AMOUNT S\$ 4,905.35

GST @ 7 % 343.37

AMOUNT DUE S\$ 5,248.72

Customer's Signature/Co. Stamp **MOVA AUTOMOTIVE PTE LTD**

- LKK Auto Consultants hence notify the Repairer of the following:
- To resurvey before/after spray painting
  - To display damaged part(s) during resurvey
  - Parts prices are subject to confirmation
  - Third party survey is on a "Without Prejudice" basis
  - No illegal modification(s) is allowed
  - Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: