



**Main Office:**

Mova Building  
No. 22, Jalan Kilang,  
Singapore 159419  
Tel: (65) 6476 3333  
Fax: (65) 6271 5891  
www.mova.com.sg

**Workshop Dept:**

Block 1008,  
Bukit Merah Lane 3,  
#01-04/06/08/94  
Singapore 159722

Tel: (65) 6272 3892  
Fax: (65) 6270 8314

Co. Reg. 198904033G  
GST Reg. M2-0088864-2

# Estimate

27/09/2022

**EQ INSURANCE CO LTD**  
**5 MAXWELL ROAD**  
**#17-00 TOWER BLOCK MND COMPLEX**  
**SINGAPORE 069110**

Attention :- XA039

*Stew (LKK)*  
*28/9/22 2-3pm*  
*n n*  
*4 djs*  
*L/S*  
*to ALY*

Page # :- 1  
Veh # :- SLP1195M  
Veh Model :- TOYOTA ALTIS  
Estimate# :- CK424044  
Claim # :-  
ACC. Date :- 27/09/22  
Terms :- C.O.D Days  
Remarks :-

No.	Description	Qty	U.Price	Amounts S\$
<b>LIST ITEMS :</b>				
1.	REAR BUMPER / <i>OD</i>	1	PC 689.50	689.50
2.	REAR BUMPER REINFORCEMENT / <i>BT</i>	1	PC 423.90	423.90
3.	REAR BUMPER SIDE RETAINER BRACKET LH / <i>BT</i>	1	PC 116.00	116.00
4.	REAR BUMPER SIDE RETAINER BRACKET RH / <i>BT</i>	1	PC 116.00	116.00
5.	REAR END PANEL	1	PC 740.90	740.90
6.	REAR END PANEL TOP COVERING / <i>?</i>	1	PC 256.60	256.60
7.	REAR SPARE TYRE UPPER BOARD / <i>?</i>	1	PC 382.80	382.80
8.	REAR TAIL LAMP RH / <i>X</i>	1	PC 472.60	472.60
9.	REAR BOOT LID "COROLLA" EMBLEM / <i>PC</i>	1	PC 56.50	56.50
10.	REAR BOOT LID "ALTIS" EMBLEM / <i>PC</i>	1	PC 58.30	58.30
11.	REAR BOOT LID "LOGO" EMBLEM / <i>PC</i>	1	PC 80.70	80.70
12.	REAR BOOT LID (REPAIR) / <i>X R</i>	1	PC	
13.	REAR QUATER PANEL RH (REPAIR) / <i>X R</i>	1	PC	
14.	REAR SPARE TYRE PANEL (REPAIR) / <i>X R</i>	1	PC	
LIST TOTAL S\$				3,393.80
25% DISCOUNT S\$ <i>* end of 1st sem</i>				-848.45
				<u>2,545.35</u>
<b>SPECIAL NET ITEMS :</b>				
1.	REAR BUMPER REVERSE SENSOR / <i>Shd</i>	1	PC 200.00	200.00
2.	REAR BUMPER CLIPS / <i>PC</i>	1	SET 40.00	40.00
3.	REAR END PANEL TOP COVERING CLIPS / <i>?</i>	1	SET 30.00	30.00
4.	REAR END PANEL JOINT SEALANT / <i>?</i>	1	PC 50.00	50.00
SPECIAL NET TOTAL S\$				<u>320.00</u>
<b>LABOUR :</b>				
TO REMOVE, REPLACE, REFIT REAR BUMPER, REVERSE SENSOR, REAR REVERSE CAMERA & ETC. TO EFFECT REPLACE OF REAR BUMPER				<i>30</i> 80.00
TO CHECK WIRING & ELECTRICAL SYSTEM				<i>30</i> 60.00
TO REMOVE, REPLACE, REPAIR, READJUST & CHISEL REAR ACCIDENT AREAS SUCH AS REAR BOOT LID, REAR END PANEL, REAR BUMPER, REAR SPARE TYRE PANEL, REAR QUATER PANEL RH & ETC. BACK TO ORIGINAL CONDITIONS				<i>400</i> 900.00
TO SUPPLY PAINT & FURNISHING MATERIALS AT REAR BUMPER, REAR END PANEL, REAR BOOT LID, REAR SPARE TYRE PANEL, REAR QUATER PANEL RH & ETC.				<i>800</i> 1,000.00
LABOUR TOTAL S\$				<u>2,040.00</u>

*bizSAFE*

**Main Office:**  
Mova Building  
No. 22, Jalan Kilang,  
Singapore 159419  
Tel: **(65) 6476 3333**  
Fax: (65) 6271 5891  
www.mova.com.sg

**Workshop Dept:**  
Block 1008,  
Bukit Merah Lane 3,  
#01-04/06/08/94  
Singapore 159722

Tel: **(65) 6272 3892**  
Fax: (65) 6270 8314  
Co. Reg. 198904033G  
GST Reg. M2-0088864-2

# Estimate

27/09/2022

**EQ INSURANCE CO LTD**  
**5 MAXWELL ROAD**  
**#17-00 TOWER BLOCK MND COMPLEX**  
**SINGAPORE 069110**

Attention :- **XA039**

Page # :- 1 147126  
Veh # :- SLP1195M  
Veh Model :- TOYOTA ALTIS  
Estimate# :- CK424044  
Claim # :-  
ACC. Date :- 27/09/22  
Terms :- C.O.D Days  
Remarks :-

No.	Description	Qty	U.Price	Amounts S\$
-----	-------------	-----	---------	-------------

E. & O.E

NON-TAX AMOUNT S

AMOUNT S\$

4,905.35

GST @ 7 %

343.37

AMOUNT DUE S\$

5,248.72

Customer's Signature/Co. Stamp **MOVA AUTOMOTIVE PTE LTD**

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: